



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D3 SE LUX
Colour	Silver
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-09-17
Pictures	41
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-16
Pictures	41
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-16
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	23
Total items failed	1

MOT #16	2024-04-17 15:52
MOT test number	221101897692
Result	✓ Passed
Next expiry date	2025-04-16

MOT #15	2024-04-17 10:08
MOT test number	494567808227
Result	✗ Failed
MAJOR Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	

MOT #14	2023-03-09 16:19
MOT test number	503613859408
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Both front tyres worn low on edges	

**MOT #13** 2023-03-09 09:54**MOT test number** 602235303097**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Both front tyres worn low on edges**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))**MOT #12** 2022-04-01 15:36**MOT test number** 585872507685**Result** ✓ Passed**MOT #11** 2022-04-01 14:29**MOT test number** 685778510632**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #10** 2021-02-17 10:45**MOT test number** 859642982818**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

**MOT #9** 2021-02-16 16:43**MOT test number** 125883334698**Result** ✗ Failed

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

MAJOR Offside Front Headlamp aim too low (4.1.2 (a))

Minor Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #8 2020-02-06 10:36**MOT test number** 491013948481**Result** ✓ Passed

Advice Nearside Front Tyre slightly worn on inner edge

MOT #7 2019-02-22 13:59**MOT test number** 131418564081**Result** ✓ Passed**MOT #6** 2019-02-22 10:03**MOT test number** 434409722656**Result** ✗ Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #5 2018-02-27 15:30**MOT test number** 544582221117**Result** ✓ Passed



MOT #4	2017-03-08 16:20
MOT test number	708283527291
Result	✓ Passed
MOT #3	2017-03-08 10:09
MOT test number	602158124403
Result	✗ Failed
<div><div>Advice</div>Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Advice</div>Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Fail</div>Offside Registration plate lamp not working (1.1.C.1d)</div>	
MOT #2	2016-02-24 13:21
MOT test number	552336859154
Result	✓ Passed
MOT #1	2015-03-16 09:56
MOT test number	126085675491
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-01
Last registration	2024-04-17
Complete history	See info



Registration #1	2012-03-01	21 mi
Registration #2	2015-03-16	29.512 mi
Registration #3	2016-02-24	33.739 mi
Registration #4	2017-03-08	37.663 mi
Registration #5	2017-03-08	37.663 mi
Registration #6	2018-02-27	41.454 mi
Registration #7	2019-02-22	45.807 mi
Registration #8	2019-02-22	45.807 mi
Registration #9	2020-02-06	49.229 mi
Registration #10	2021-02-16	51.393 mi
Registration #11	2022-02-22	55.277 mi
Registration #12	2022-02-22	55.277 mi
Registration #13	2023-02-22	59.277 mi
Registration #14	2023-02-22	59.277 mi
Registration #15	2024-02-22	63.277 mi
Registration #16	2024-02-22	63.277 mi
Registration #17	2024-02-22	63.277 mi
Registration #18	2024-02-22	63.277 mi
Registration #19	2024-02-22	63.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1773 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	995146
---------------	--------