





report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	BEETLE TDI 105BHP
Colour	Blue
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

## Entry 1

Date 2021-08-06

Pictures 38

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## **MOT** history

MOT expiry date	2024-08-01
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	15
Total items failed	1

MOT #17	2023-08-01 09:44
MOT test number	432088688999
Result	✓ Passed
Next expiry date	2024-08-01

MOT #16	2023-07-31 09:47
MOT test number	983234017881
Result	<b>×</b> Failed

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #15	2022-08-02 13:34
MOT test number	399069001847
Result	✓ Passed

MOT #14	2022-08-01 14:19
MOT test number	365100492332
Result	<b>≍</b> Failed

MAJOR Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13	2021-06-14 09:49

MOT test number 884425845466

MOT #12 2020-06-16 09:17

**MOT test number** 878636855439

**Result** ✓ Passed

**MOT #11** 2019-06-04 12:31

**MOT test number** 561913177439

**Result** ✓ Passed

MOT #10 2018-06-13 08:56

**MOT test number** 632425911249

**MOT #9** 2018-06-12 09:41

**MOT test number** 559267663856

Result X Failed

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #8 2017-06-02 11:58

**MOT test number** 880965556569

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2016-06-02 16:23

**MOT test number** 349477087841

**Result** 
✓ Passed

MOT #6 2016-06-01 13:15

MOT test number 773787428151

Result X Failed

**Advice** Offside Rear near limit

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2015-04-02 09:21

**MOT test number** 656062795091

Result \rightarrow Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2014-04-04 14:10

MOT test number 597834794011

Result \( \sqrt{Passed} \)

**Advice** Tyre worn close to the legal limit (4.1.E.1)

**Advice** Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2013-03-23 10:46

MOT test number 885062783085

Result / Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/13



Result

YP08VWK

report date: 2024-03-28

✓ Passed

 MOT #2
 2012-03-22 16:07

 MOT test number
 148532082083

 Result
 ✓ Passed

 MOT #1
 2011-10-06 15:27

 MOT test number
 485419971219

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	1 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-28

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

# Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
manus .	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NE SIE
Plate since	

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-30
Last registration	2023-08-01
Complete history	See info



Registration #1	2008-04-30	26 mi
Registration #2	2011-10-06	17.469 mi
Registration #3	2012-03-22	19.374 mi
Registration #4	2013-03-23	28.782 mi
Registration #5	2014-04-04	36.708 mi
Registration #6	2015-04-02	44.737 mi
Registration #7	2016-06-01	52.957 mi
Registration #8	2016-06-02	52.958 mi
Registration #9	2017-06-02	59.645 mi
Registration #10	2018-06-12	66.416 mi
	2018-06-12	66.416 mi
Registration #10		66.416 mi
Registration #10 Registration #11		66.416 mi
Registration #10 Registration #11 Registration #12		66.416 mi
Registration #10 Registration #11 Registration #12 Registration #13		66.416 mi
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		66.416 mi
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		66.416 mi
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		66.416 mi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1460 kg
Max. allowed weight	1840 kg

# Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
CarChaels on uls	200 12/1

CarCheck.co.uk page 13/13

Number of seats	4
Number of axles	2
Engine number	BSW 017167