



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 R-LINE TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	-
Top speed	140 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	258 BHP
Max. torque	550 Nm at 1.750 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.8 mpg





Internet history

Entry 1

Date	2021-09-05
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

**MOT history**

<b>MOT #5</b>	2022-09-15 13:58
<b>MOT test number</b>	920185171930
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-09-17

<b>MOT #4</b>	2021-09-18 10:25
<b>MOT test number</b>	490590264243
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2020-11-20 15:54
<b>MOT test number</b>	966577419444
<b>Result</b>	✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing also on 3mm (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened slight lip on discs (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing also on 3mm (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #2</b>	2020-11-19 13:02
<b>MOT test number</b>	494198228304
<b>Result</b>	✗ Failed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened slight lip on discs (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing also on 3mm (5.2.3 (d) (ii))
- Fail** Offside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing also on 3mm (5.2.3 (d) (ii))

<b>MOT #1</b>	2019-11-01 16:07
<b>MOT test number</b>	202070124587
<b>Result</b>	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>RF66CKL</b>
Plate since	2019-06-29
Current registration	 <b>RF66CKL</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2016-11-29
Last registration	2022-09-15
Complete history	<a href="#">See info</a>



Registration #1	2016-11-29	21 mi
Registration #2	2019-11-01	33.874 mi
Registration #3	2020-11-19	38.724 mi
Registration #4	2020-11-20	38.724 mi
Registration #5	2022-09-15	38.724 mi
Registration #6	2022-09-15	38.724 mi
Registration #7	2022-09-15	38.724 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2208 mm
Height	1732 mm
Length	4889 mm
Wheel base	2893 mm
Kerb weight	2185 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CVVA059204