





report date: 2024-03-28

### General information

Make	FIAT
Model	500 L POP STAR
Colour	White
Year of manufacture	2013
Top speed	111 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-08-06

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-08-25
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	15
Total items failed	13

MOT #12	2023-08-24 15:59
MOT test number	732756887690
Result	✓ Passed
Next expiry date	2024-08-25

мот #	<b>11</b> 2023-08-23 15:4	7
MOT te	947516960633	2
Result	× Failed	d
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Nearside Brake cable damaged SNAPPED (1.1.15 (a))	
Fail	Nearside Parking brake inoperative on one side (1.4.1 (a))	
Fail (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b)	

MOT #10	2022-08-22 14:15
MOT test number	981935040506
Result	<b>✓</b> Passed
Advice Front Exhaust has a minor leak of exhaust gases Flexible joint (6.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice


Front Exhaust has a minor leak of exhaust gases Flexible joint (6.1.2 (a))

Advice Front Exhaust has a minor leak of exhaust gases Flexible joint (6.1.2 (a))	
MOT #8	2021-08-26 13:34
MOT test number	962780685218
Result	✓ Passed
MOT #7	2021-01-21 14:59
MOT test number	111486237346
Result	✓ Passed
MOT #6	2021-01-21 14:59
MOT test number	647004236532
Result	<b>X</b> Failed
Pass with rectification all lamps (4.7.1 (b) (ii))	Offside Rear Registration plate lamp inoperative in the case of a single lamp or

CarCheck.co.uk page 4/13



report date: 2024-03-28



MOT #4		2019-08-23 10:29
MOT test	number	848677453242
Result		✓ Passed
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing perishing	(5.2.3 (d) (ii))
Advice	Slight bind in rear brakes	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excession	ve movement (5.3.4 (a)
Advice	Offside Rear taillight lens scratched	
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing perishing (	5.2.3 (d) (ii))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3		2018-08-10 11:11
MOT test	number	515578370375
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	

MOT #2	2017-08-24 12:00
MOT test number	385345896742
Result	✓ Passed
MOT #1	2016-12-01 12:30
MOT test number	315574819399
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

$\sim$		100		
( ) v	vner	his	:tor	٦.
$\sim$ v	$\mathbf{v} \cap \mathbf{v}$		וטא	

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
*********	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	IK NEW YORK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-11-28
Last registration	2023-08-24
Complete history	See info



Registration #1	2013-11-28	14 mi
Registration #2	2016-12-01	20.522 mi
Registration #3	2017-08-24	24.462 mi
Registration #4	2018-08-10	31.792 mi
Registration #5	2019-08-23	38.302 mi
Registration #6	2020-09-19	44.395 mi
Registration #7	2021-01-21	44.442 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	1780 mm
Height	1660 mm
Length	4140 mm
Max. allowed weight	1805 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	4016273

CarCheck.co.uk page 13/13