





report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.800 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	194 g/km
CO2 label	J



CarCheck.co.uk page 1/12



VN11FXP

report date: 2024-03-29

Internet history

Entry 1


Date 2021-08-28


Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-09
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	11
Total items failed	7

MOT #14	2023-09-06 16:00
MOT test number	107353136481
Result	✓ Passed
Next expiry date	2024-09-09
Advice Nearside Front Outer tyre wall damage	

MOT #13		2023-09-06 16:00
MOT test number		384198290912
Result		X Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front Outer tyre wall damage		
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	
Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))		

MOT #12	2022-09-10 13:43
MOT test number	370074622878
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #11 2022-09-09 12:49

MOT test number 274485577508

Result X Failed

Fail Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10 2021-09-03 10:22

MOT test number 505858163454

Result \square Passed

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #9 2020-11-18 17:16

MOT test number 405727917976

Result ✓ Passed

MOT #8 2020-03-03 09:19

MOT test number 434562818243

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view small (3.2 (a) (i))

Advice Front brakes worn low

MOT #7 2019-03-05 09:14

MOT test number 787965472454

Minor Windscreen damaged but not adversely affecting driver's view small (3.2 (a) (i))

Minor Rear Windscreen wiper blade defective split (3.4 (b) (i))

CarCheck.co.uk page 4/12



VN11FXP

report date: 2024-03-29

MOT #6 2018-03-12 10:28 MOT test number 354287574232

MOT #5 2017-03-08 10:52

MOT test number 591639527827

Result
✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2016-03-10 10:41

MOT test number 490686122705

Result ✓ Passed

MOT #3 2016-03-10 10:41

MOT test number 842582609679

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively

(8.2.2)

MOT #2 2015-03-16 10:11

MOT test number 437275875035

Result ✓ Passed

MOT #1 2014-03-12 10:09

MOT test number 758451674058

Result \(\sqrt{Passed} \)

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	9 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

•		
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		

	More info	>
Plate changes See in this check if this KIA had different number plates.		
Number of plates		,
Current registration	UK NEZ	
Plate since		
Current registration	UK Min	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-28
Last registration	2023-09-06
Complete history	See info



Registration #1	2011-04-28	17 mi
Registration #2	2014-03-12	30.484 mi
Registration #3	2015-03-16	44.673 mi
Registration #4	2016-03-10	54.594 mi
Registration #5	2016-03-10	54.594 mi
Registration #6	2017-03-08	68.277 mi
Registration #7	2018-03-12	79.322 mi
Registration #8	2019-03-05	89.538 mi
Registration #9		11.777 66
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.177 es
Registration #13		11.177 es
Registration #14		D.777 es
Registration #15		11.177 mi

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/

Engine number

D4HBBH030559