



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Blue
Year of manufacture	2006
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-30
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	37
Total items failed	17

MOT #18	2023-08-25 14:56
MOT test number	339239122482
Result	✓ Passed
Next expiry date	2024-08-24
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #17**

2023-08-24 11:13

**MOT test number**

817904631698

**Result**

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Body component corroded and likely to cause injury NEAR SIDE front and OFFSIDE rear (6.2.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Rear Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Rear Seat belt buckle damaged 3 rear seat belt buckles damaged (7.1.2 (d))

**MOT #16**

2022-08-10 13:50

**MOT test number**

290574443587

**Result**

✓ Passed

- Advice** Front brake discs poor, nsf tyre tread low, osr tyre inner tread low. uneven tyre tread wear, nsf shocker oily, brake judder
- Advice** Seatbelt buckles poor, rear seats not in use, rear wiper poor, car scruffy-valet needed, sills rusting-paint peel, engine oil maxxed-dirty, oil leak, osr linkbar play, bottom cover loose

**MOT #15**

2022-08-09 10:54

**MOT test number**

934509686679

**Result**

✗ Failed

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Front brake discs poor, nsf tyre tread low, osr tyre inner tread low. uneven tyre tread wear, nsf shocker oily, brake judder

**Fail** Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt outer (6.1.7 (g) (ii))

**Advice** Seatbelt buckles poor, rear seats not in use, rear wiper poor, car scruffy-valet needed, sills rusting-paint peel, engine oil maxxed-dirty, oil leak, osr linkbar play, bottom cover loose

**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**Fail** Tailgate component likely to become detached catch loose (6.2.1 (a) (ii))

**Fail** Supplementary restraint system warning lamp indicates a fault investigate - reset (7.1.6 (a))

**Fail** Nearside Headlamp aim too low (4.1.2 (a))

**MOT #14**

2021-08-23 15:04

**MOT test number**

889879926473

**Result**

✓ Passed

**Advice** Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Front Service brake binding but not excessively (1.2.1 (f))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #13** 2020-08-25 17:53**MOT test number** 518027440621**Result** ✓ Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-08-21 15:58**MOT test number** 482587035082**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both tyre has inner wear (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front passenger door catch deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))**MOT #11** 2018-08-21 08:19**MOT test number** 649170602300**Result** ✓ Passed**Advice** Nearside Front CV boot deteriorating.**Advice** Nearside Rear seat belt stalk cover missing.**MOT #10** 2017-08-16 11:11**MOT test number** 787518908807**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #9** 2016-08-24 10:59**MOT test number** 997192793763**Result** ✓ Passed

**MOT #8** 2015-08-11 14:17**MOT test number** 398353564909**Result** ✓ Passed**MOT #7** 2015-08-11 09:37**MOT test number** 621854205890**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2014-03-04 10:16**MOT test number** 615763464039**Result** ✓ Passed**MOT #5** 2013-03-04 17:03**MOT test number** 165933263013**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-03-09 14:34**MOT test number** 997839262047**Result** ✓ Passed**MOT #3** 2012-03-07 16:51**MOT test number** 769657162094**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)



MOT #2	2011-03-03 17:23
MOT test number	237352461076
Result	✓ Passed

MOT #1	2009-11-19 12:31
MOT test number	201653629387
Result	✓ Passed

- Notice

Nsr/osr bump stops poor
- Advice

Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

Handbrake just passed performance test
- Advice

Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

Vehicle needs to be cleaned before next mot,as refusal to test can be issued.





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
24 August 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	24 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>FP56BZC</b>
Plate since	2024-03-28
Current registration	 <b>FP56BZC</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-12-11
Last registration	2023-08-25
Complete history	<a href="#">See info</a>



Registration #1	2006-12-11	13 mi
Registration #2	2009-11-19	83.531 mi
Registration #3	2011-03-03	106.732 mi
Registration #4	2012-03-07	108.166 mi
Registration #5	2012-03-09	108.167 mi
Registration #6	2013-03-04	114.340 mi
Registration #7	2014-03-04	117.912 mi
Registration #8	2015-08-11	12.658 mi
Registration #9	2015-08-11	126.587 mi
Registration #10	2016-08-24	132.208 mi
Registration #11	2016-08-24	132.208 mi
Registration #12	2016-08-24	132.208 mi
Registration #13	2016-08-24	132.208 mi
Registration #14	2016-08-24	132.208 mi
Registration #15	2016-08-24	132.208 mi
Registration #16	2016-08-24	132.208 mi
Registration #17	2016-08-24	132.208 mi
Registration #18	2016-08-24	132.208 mi
Registration #19	2016-08-24	132.208 mi
Registration #20	2016-08-24	132.208 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE 028165