





report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



Internet history

Entry 2


Date	2021-07-30
Pictures	0
Listing price	<u>View report</u>

source: cargurus.co.uk

Entry 1

Date	2021-07-29	
Pictures	24	
Listing price	View report	









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-05-06
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	20
Total items failed	8

MOT #11		2021-05-07 08:53
MOT test	number	747502990957
Result		✓ Passed
Next expiry date 2022-05-		2022-05-06
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10			2021-05-07 08:53
MOT test no	umber		798949277648
Result			X Failed
Pass with	rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))			
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))			

CarCheck.co.uk page 3/13



MOT #9 2020-12-21 10:38

MOT test number 535492893271

Result ✓ Passed

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge starting to wear out of shape (5.2.3

(e))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge starting to wear out of shape

(5.2.3 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8 2019-12-18 10:22

MOT test number 772395776474

Result ✓ Passed

MOT #7 2019-01-08 14:58

MOT test number 407869583567

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Service light on

MOT #6 2019-01-08 12:18

MOT test number 329698247657

Result X Failed

Advice Service light on

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



WA13VLZ

report date: 2024-03-28

✓ Passed

 MOT #5
 2018-01-11 14:40

 MOT test number
 962475146093

 Result
 ✓ Passed

MOT #4 2018-01-09 15:13

MOT test number 528374603567

Result × Failed

Fail Parking brake efficiency below requirements (3.7.E.1)

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

 MOT #3
 2017-01-18 09:15

 MOT test number
 362738438187

MOT #2 2016-03-29 08:55

MOT test number 591536557978

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Sump dented

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear wiper blade split

CarCheck.co.uk page 5/13



MOT #1 2016-03-29 08:55

MOT test number 439212197877

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Sump dented

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear wiper blade split

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax expired: 27 September 2021

MOT Expired: 6 May 2022

Tax status	Expired at 27 September
Days left	944 days too late
MOT expiry date	6 May 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	IK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-21
Last registration	2021-05-07
Complete history	See info



Registration #1	2013-03-21	28 mi
Registration #2	2016-03-29	16.953 mi
Registration #3	2016-03-29	16.953 mi
Registration #4	2017-01-18	21.314 mi
Registration #5	2018-01-09	30.781 mi
Registration #6	2018-01-11	30.841 mi
Registration #7	2019-01-08	42.638 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ

CarCheck.co.uk page 13/13