





report date: 2024-03-29

General information

Make	MAZDA
Model	3 SE-L NAV
Colour	Red
Year of manufacture	2016
Top speed	121 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-15

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



SY66UPW report date: 2024-03-29

MOT history

MOT expiry date	2025-02-26
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #8		2024-02-27 16:01
MOT test i	number	880072087338
Result		✓ Passed
Next expir	y date	2025-02-26
Advice	Offside Front windscreen washer fluid leak (possibly from bottle)	
Advice bush peris	Offside Front Suspension arm pin or bush worn but not resulting in exc ned and split (5.3.4 (a) (i))	essive movement rear most
Advice most bush	Nearside Front Suspension arm pin or bush worn but not resulting in experished and split (5.3.4 (a) (i))	xcessive movement rear

MOT #7	2024-02-26 17:30
MOT test number	308308705909
Result	× Failed
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracked and close to the (ii))	ne limit (5.2.3 (d)
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive r most bush perished and split (5.3.4 (a) (i))	movement rear
Fail Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened dis (ii))	k red (1.1.14 (a)
Advice Offside Front windscreen washer fluid leak (possibly from bottle)	
Fail Brake lever has insufficient reserve travel (1.1.2 (a))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive mobush perished and split (5.3.4 (a) (i))	ovement rear most

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2022-05-30 11:12

MOT test number 637729064118

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front brake discs pitted/scored

MOT #5 2022-05-27 09:26

MOT test number 726850960337

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front brake discs pitted/scored

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2021-06-11 13:22

MOT test number 846610802182

Result ✓ Passed

MOT #3 2021-06-11 07:58

MOT test number 877461609611

Result × Failed

Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2020-09-14 10:56

MOT test number 142090663005

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2019-08-29 13:46

MOT test number 427338943043

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full		A

	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Flate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-26
Last registration	2024-02-27
Complete history	See info



Registration #1	2016-09-26	20 mi
Registration #2	2019-08-29	14.180 mi
Registration #3	2020-09-14	20.021 mi
Registration #4	2021-06-11	24.387 mi
Registration #5	2021-06-11	24.389 mi
Registration #6		11.117 es
Registration #7		11.777 es
Registration #8		
Registration #8 Registration #9		11.77 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1465 mm
Length	4465 mm
Wheel base	2700 mm
Kerb weight	1205 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	51
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	PE 20725669

CarCheck.co.uk page 12/12