




report date: 2025-02-17

General information

Make	VOLVO
Model	S40 D DRIVE R-DESIGN
Colour	Black
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-05-26
Pictures	38
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	10
Total items failed	9

MOT #15	2024-04-03 08:48
MOT test number	227381542585
Result	✓ Passed
Next expiry date	2025-04-04

MOT #14	2023-03-29 10:15
MOT test number	573731356800
Result	✓ Passed

MOT #13	2022-04-04 08:58
MOT test number	945683045152
Result	✓ Passed

MOT #12	2022-04-04 08:58
MOT test number	650149223552
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11	2021-03-25 13:33
MOT test number	656510848755
Result	✓ Passed



MOT #10	2020-03-31 11:17
MOT test number	243457610118
Result	✓ Passed

MOT #9	2020-03-25 09:42
MOT test number	392669215827
Result	✗ Failed

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #8	2019-03-28 18:04
MOT test number	507183031149
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge BOTH EDGES (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view ZONE A (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))



MOT #7 2019-03-27 09:34

MOT test number 708198454819

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge BOTH EDGES (5.2.3 (e))
- Fail** Offside Rear Hydraulic brake calliper leaking and braking performance affected (1.1.16 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view ZONE A (3.2 (a) (i))

MOT #6 2018-04-05 11:37

MOT test number 409825123570

Result ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Rear Brake pad(s) wearing thin on limit. (3.5.1g)
- Advice** Nearside Rear Inner Tyre worn close to the legal limit edge (4.1.E.1)
- Advice** Offside Rear Inner Tyre worn close to the legal limit edge on limit. (4.1.E.1)

MOT #5 2017-03-31 07:29

MOT test number 592150369600

Result ✓ Passed

MOT #4 2016-03-23 11:27

MOT test number 341884075480

Result ✓ Passed

MOT #3 2015-03-19 11:26

MOT test number 787888075004

Result ✓ Passed



MOT #2 2014-03-13 10:12

MOT test number 387302374085

Result ✓ Passed

MOT #1 2013-03-13 12:46

MOT test number 918192373047

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 September 2025

✓
MOT

Expires:
4 April 2025

Tax status Valid until 1 September

Days left 168

MOT expiry date 4 April 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2025-02-17
Current registration	XXXXX
Plate since	2025-02-17

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2024-04-03
Complete history	See info



Registration #1	2010-03-31	12 mi
Registration #2	2013-03-13	19.633 mi
Registration #3	2014-03-13	27.590 mi
Registration #4	2015-03-19	32.996 mi
Registration #5	2016-03-23	38.021 mi
Registration #6	2017-03-31	42.773 mi
Registration #7	2018-04-05	53.720 mi
Registration #8	2019-03-27	61.116 mi
Registration #9	2019-03-28	61.125 mi
Registration #10	2019-03-28	61.125 mi
Registration #11	2019-03-28	61.125 mi
Registration #12	2019-03-28	61.125 mi
Registration #13	2019-03-28	61.125 mi
Registration #14	2019-03-28	61.125 mi
Registration #15	2019-03-28	61.125 mi
Registration #16	2019-03-28	61.125 mi
Registration #17	2019-03-28	61.125 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553