



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Black
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-09-01
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-07
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-05
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	19
Total items failed	7

MOT #15	2023-07-12 17:10
MOT test number	216226389719
Result	✓ Passed
Next expiry date	2024-08-05
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2022-08-04 08:38
MOT test number	597049572361
Result	✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13** 2022-08-03 15:48**MOT test number** 115504042358**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #12** 2021-08-06 07:18**MOT test number** 209315704711**Result** ✓ Passed**MOT #11** 2020-10-15 12:11**MOT test number** 503277982456**Result** ✓ Passed**MOT #10** 2019-10-04 09:33**MOT test number** 967102086894**Result** ✓ Passed**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated top boot (5.3.4 (b) (i))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated top boot (5.3.4 (b) (i))**MOT #9** 2018-10-25 15:20**MOT test number** 555289167435**Result** ✓ Passed

**MOT #8** 2017-11-10 13:18**MOT test number** 156664690717**Result** ✓ Passed**MOT #7** 2016-11-25 11:12**MOT test number** 537919002057**Result** ✓ Passed**MOT #6** 2015-11-25 14:19**MOT test number** 785165839158**Result** ✓ Passed**MOT #5** 2015-11-25 10:54**MOT test number** 816934669457**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt droplink (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt droplink (2.4.G.2)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2014-11-26 10:39**MOT test number** 486930934365**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-10-31 15:13
MOT test number	909644103398
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2012-10-25 16:34
MOT test number	347109992477
Result	✓ Passed

MOT #1	2011-10-12 13:33
MOT test number	398715781434
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
5 August 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 CK58FKO
Plate since	2019-09-29
Current registration	 CK58FKO
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-13
Last registration	2023-07-12
Complete history	See info



Registration #1	2008-10-13	17 mi
Registration #2	2011-10-12	14.130 mi
Registration #3	2012-10-25	17.773 mi
Registration #4	2013-10-31	20.199 mi
Registration #5	2014-11-26	23.943 mi
Registration #6	2015-11-25	28.248 mi
Registration #7	2015-11-25	28.248 mi
Registration #8	2016-11-25	32.108 mi
Registration #9	2017-11-10	34.346 mi
Registration #10	2018-11-10	35.377 mi
Registration #11	2019-11-10	35.377 mi
Registration #12	2020-11-10	35.377 mi
Registration #13	2021-11-10	35.377 mi
Registration #14	2022-11-10	35.377 mi
Registration #15	2023-11-10	35.377 mi
Registration #16	2024-11-10	35.377 mi
Registration #17	2025-11-10	35.377 mi
Registration #18	2026-11-10	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1078130