



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D INVINCIBLE AWD
Colour	Beige
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-30
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-24
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	44
Total items failed	8

MOT #13	2023-09-21 11:55
---------	------------------

MOT test number	771996314795
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-24
------------------	------------

- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sills (5.3.6 (a) (i))
- Advice

Vehicles internal headlight adjuster altered to recheck lights
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Rear Lower Suspension component mounting prescribed area damaged but not considered excessive inner sills (5.3.6 (a) (i))

**MOT #12**

2023-09-20 12:54

MOT test number

243875407961

Result**✗ Failed****Fail**

Offside Rear Anti-roll bar attachment bracket/mounting insecure (5.3.3 (a) (i))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Vehicles internal headlight adjuster altered to recheck lights

Advice

Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive inner sills (5.3.6 (a) (i))

Fail

Nearside Rear Anti-roll bar attachment bracket/mounting insecure (5.3.3 (a) (i))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Rear Lower Suspension component mounting prescribed area damaged but not considered excessive inner sills (5.3.6 (a) (i))

MOT #11

2022-09-07 12:56

MOT test number

617165186401

Result**✓ Passed****Advice**

Offside Front Nail in tyre

MOT #10

2022-09-07 11:16

MOT test number

627313416236

Result**✗ Failed****Advice**

Offside Front Nail in tyre

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail

Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail

Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2021-09-25 15:05**MOT test number** 153520194613**Result** ✓ Passed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2021-04-01 15:13**MOT test number** 471596665379**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive surface corrosion (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-06-26 13:46**MOT test number** 534277296959**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** TYRE REPAIR SEALANT OUT OF DATE**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #6** 2019-06-21 15:33**MOT test number** 817056567920**Result** ✗ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** TYRE REPAIR SEALANT OUT OF DATE

MOT #5 2018-05-03 13:06**MOT test number** 244281736007**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2018-05-03 09:37**MOT test number** 738776485993**Result** ✗ Failed

- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2017-05-11 13:02**MOT test number** 263731232485**Result** ✓ Passed**Advice** Offside rear tyre inner sidewall split/cut**Advice** Rear brake discs corroded and scored**Advice** Front wiper blades starting to smear**Advice** Rear brake pads worn low**Advice** Slight fluctuation at rear brakes**MOT #2** 2017-05-11 10:55**MOT test number** 539428271380**Result** ✗ Failed**Advice** Slight fluctuation at rear brakes**Advice** Offside rear tyre inner sidewall split/cut**Advice** Rear brake discs corroded and scored**Advice** Front wiper blades starting to smear**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
inner sidewall cut (4.1.D.1a)**Advice** Rear brake pads worn low**MOT #1** 2016-05-20 14:55**MOT test number** 553262186396**Result** ✓ Passed**Advice** Engine cover and under trays fitted at time of test



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-05-30
Last registration	2023-09-21
Complete history	See info



Registration #1	2013-05-30	26 mi
Registration #2	2016-05-20	46.137 mi
Registration #3	2017-05-11	56.002 mi
Registration #4	2017-05-11	56.002 mi
Registration #5	2018-05-03	63.185 mi
Registration #6	2018-05-03	63.187 mi
Registration #7	2019-06-21	77.869 mi
Registration #8	2019-06-26	77.869 mi
Registration #9	2020-05-20	95.277 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2020-05-20	95.277 mi
Registration #12	2020-05-20	95.277 mi
Registration #13	2020-05-20	95.277 mi
Registration #14	2020-05-20	95.277 mi
Registration #15	2023-09-21	115.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1845 mm
Height	1705 mm
Length	4570 mm
Wheel base	2570 mm
Kerb weight	1660 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0412140