



AJ18ENM

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V HIGHLINE BMT
Colour	White
Year of manufacture	2018
Top speed	94 mph
0 - 100 km/h	11.6 seconds
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 101 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-03-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-21
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #4	2023-08-22 09:35
MOT test number	590153070196
Result	✓ Passed
Next expiry date	2024-08-21
Minor	Front Lower Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))

MOT #3	2023-08-21 14:05
MOT test number	675106593178
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Front Lower Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))



MOT #2 2022-03-25 11:46

MOT test number 528513372532

Result ✓ Passed

- Minor** Front Windscreen damaged but not adversely affecting driver's view 3 Chips In Windscreen (3.2 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tyre On 2mm. (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #1 2021-07-09 13:34

MOT test number 538578718534

Result ✓ Passed

- Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both front arm rear bushes deteriorated. (5.3.4 (a) (i))
- Advice** Stone chip in windscreen.



Tax & MOT check

X

Untaxed

Tax expired:
31 July 2023

✓

MOT

Expires:
21 August 2024

Tax status	Expired at 31 July 2023
Days left	274 days too late
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-07-13
Last registration	2023-08-22
Complete history	See info



Registration #1	2018-07-13	6 mi
Registration #2	2021-07-09	181.373 mi
Registration #3	2023-08-22	201.373 mi
Registration #4	2023-08-22	201.373 mi
Registration #5	2023-08-22	201.373 mi
Registration #6	2023-08-22	201.373 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2397 mm
Height	1990 mm
Length	5304 mm
Wheel base	3400 mm
Kerb weight	1942 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	3
Number of axles	2
Engine number	CXGB122204