





General information

Make	PEUGEOT
Model	107 ALLURE
Colour	Black
Year of manufacture	2013
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP	0 < 101 A
Max. torque	93 Nm at 3.600 rpm	101 - 120 ^B _C
ngine capacity	998 cc	121 - 140 P
ylinders	3	141 - 165 F
uel type	Petrol	166 - 185
consumption city	55.4 mpg	186 - 225
onsumption extra urban	74.3 mpg	225+
onsumption combined	65.7 mpg	
CO2 emission	99 g/km	
CO2 label	А	





Internet history

Entry 1

Date

Pictures

2021-10-02

17

Listing price

View report







source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	19
Total items failed	6

MOT #11	2023-10-16 13:57
MOT test number	680120212332
Result	✓ Passed
Next expiry date	2024-10-15

MOT #10	2022-09-27 14:30
MOT test number	349750090832
Result	✓ Passed

MOT #9		2021-09-17 12:03
MOT test	number	680913658295
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Items removed from driver's view prior to test	



МОТ #8	2021-09-17 11:06
MOT test number	658601188658
Result	🗙 Failed
Advice Items removed from driver's view prior to test	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm 155/65/14	4 (5.2.3 (e))
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to real 155/65/14 (5.2.3 (d) (i))	ach the ply or cords
FailNearside Rear Inner Tyre has a bulge, caused by separation or partial failure155/65/14 (5.2.3 (d) (ii))	of its structure
Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm 155/65/14 ((5.2.3 (e))
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to r 155/65/14 (5.2.3 (d) (i))	each the ply or cords

MOT #7	2020-09-21 09:29
MOT test number	963754072261
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in e (5.3.4 (a) (i))	excessive movement
Advice Rear Tyre worn close to legal limit/worn on edge both rear tyres close to lin perished/cracking (5.2.3 (e))	mit and
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	n excessive movement

MOT #6	2019-04-16 11:59
MOT test number	100087918899
Result	✓ Passed

KR13HYB

report date: 2024-03-28

Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Coolant leak
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4





MOT #5	2019-04-16 10:44
MOT test number	692879472578
Result	🗙 Failed
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to r (5.2.3 (d) (i))	each the ply or cords
Advice Coolant leak	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excess (i))	ive movement (5.3.4 (a)
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in exces (a) (i))	ssive movement (5.3.4
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #4	2018-04-18 13:19
MOT test number	776663143759
Result	✓ Passed

МОТ #3	2018-04-18 09:48
MOT test number	593246284605
Result	🗙 Failed
Fail Nearside Registration plate lamp insecure (1.1.C.1c)	

MOT #2	2017-04-27 15:30
MOT test number	127998544838
Result	✓ Passed

MOT #1	2016-04-28 11:28
MOT test number	557149349878
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ мот
Tax due: 1 November 2024	Expires: 15 October 2024
Tax status	Valid until 1 November
Days left	187
MOT expiry date	15 October 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48

venicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plate	5.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-20
Last registration	2023-10-16
Complete history	<u>See info</u>



Registration #1	2013-05-20	23 mi
Registration #2	2016-04-28	29.686 mi
Registration #3	2017-04-27	40.509 mi
Registration #4	2018-04-18	49.605 mi
Registration #5	2018-04-18	49.607 mi
Registration #6	2019-04-16	60.405 mi
Registration #7	2019-04-16	60.405 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10. 200 and
Registration #11		11.227 mi
Registration #11 Registration #12		10.000 est



KR13HYB report date: 2024-03-28

Car features

S0225	Air conditioning
\$0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	905 kg
Max. allowed weight	1190 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	7422370