




report date: 2024-03-29

General information

Make	NISSAN
Model	NOTE ACENTA PREMIUM
Colour	Blue
Year of manufacture	2014
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-03-04
Pictures	8
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	10
Total items failed	0
MOT #8	2024-01-30 10:12
MOT test number	945525828877
Result	✓ Passed
Next expiry date	2025-02-01
MOT #7	2023-01-31 10:14
MOT test number	502412283186
Result	✓ Passed
MOT #6	2022-01-26 12:52
MOT test number	212172936551
Result	✓ Passed
MOT #5	2021-02-02 10:00
MOT test number	406922352793
Result	✓ Passed

**MOT #4**

2020-03-06 11:00

**MOT test number**

453757120363

**Result**

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing starting to crack on tread + outer sidewall (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing starting to perish and crack on outer sidewall (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perished + cracking on outer sidewall (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing starting to perish and crack on outer sidewall (5.2.3 (d) (ii))

**MOT #3**

2019-02-11 11:05

**MOT test number**

191513788069

**Result**

✓ Passed

**MOT #2**

2018-03-10 09:33

**MOT test number**

174167045267

**Result**

✓ Passed

- Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #1**

2017-02-06 09:32

**MOT test number**

998133467279

**Result**

✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
1 February 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	1 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-03-03
Last registration	2024-01-30
Complete history	<a href="#">See info</a>



Registration #1	2014-03-03	9 mi
Registration #2	2017-02-06	15.848 mi
Registration #3	2018-03-10	21.333 mi
Registration #4	2019-02-11	25.880 mi
Registration #5	2020-03-06	32.442 mi
Registration #6	2020-03-06	32.442 mi
Registration #7	2020-03-06	32.442 mi
Registration #8	2020-03-06	32.442 mi
Registration #9	2020-03-06	32.442 mi
Registration #10	2020-03-06	32.442 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1036 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	002116