



TOYOTA



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | TOYOTA |
| Model | LANDCRUISER VX |
| Colour | Silver |
| Year of manufacture | 2001 |
| Top speed | 109 mph |
| 0 - 60 mph | 11.7 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 232 BHP |
| Max. torque | 434 Nm at 3.400 rpm |
| Engine capacity | 4.686 cc |
| Cylinders | 8 |
| Fuel type | Petrol |
| Consumption city | 12.6 mpg |
| Consumption extra urban | 21.2 mpg |
| Consumption combined | 17.0 mpg |
| CO2 emission | 405 g/km |
| CO2 label | M |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-05 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-02 |
| MOT pass rate | 78 % |
| MOT passed | 18 |
| Failed MOT tests | 5 |
| Total advice items | 31 |
| Total items failed | 21 |

| | |
|------------------|---|
| MOT #23 | 2024-04-03 08:23 |
| MOT test number | 747382519174 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-02 |
| Advice | Both rear seats and seatbelts removed at time of test |
| Advice | Offside Front Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Nearside Rear Inner wheel arch corroded outside prescribed area |
| Advice | Nearside Front Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Offside Rear seatbelt missing |

**MOT #22**

2024-03-25 09:00

MOT test number

707498934384

Result

✗ Failed

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Rear Seat belt damaged (7.1.2 (b) (i))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Rear Inner wheel arch corroded outside prescribed area**Fail** Nearside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Both rear seats and seatbelts removed at time of test**MOT #21**

2021-11-30 11:07

MOT test number

539777751122

Result

✓ Passed

Advice Vehicle been undersealed**MOT #20**

2021-11-26 12:06

MOT test number

867103977886

Result

✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Windscreen wiper not working (3.4 (a))



| | |
|------------------------|------------------|
| MOT #19 | 2021-05-08 12:30 |
| MOT test number | 599055440092 |
| Result | ✓ Passed |
| MOT #18 | 2020-02-25 09:58 |
| MOT test number | 717745961580 |
| Result | ✓ Passed |
| MOT #17 | 2019-03-05 09:52 |
| MOT test number | 613804427537 |
| Result | ✓ Passed |
| MOT #16 | 2018-03-03 09:34 |
| MOT test number | 518733112579 |
| Result | ✓ Passed |
| MOT #15 | 2017-03-13 15:47 |
| MOT test number | 621487821034 |
| Result | ✓ Passed |
| MOT #14 | 2016-02-09 14:50 |
| MOT test number | 472946782386 |
| Result | ✓ Passed |
| MOT #13 | 2015-01-31 10:50 |
| MOT test number | 215881235027 |
| Result | ✓ Passed |

**MOT #12** 2014-07-03 15:13**MOT test number** 386974284140**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #11** 2014-07-01 16:02**MOT test number** 227942684428**Result** ✗ Failed**Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)**Fail** Offside Rear Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #10** 2013-03-08 16:54**MOT test number** 606827163089**Result** ✓ Passed**Notice** Osf height sensor bracket snapped.**Notice** Rear seats not fitted unable to check rear seatbelts.**MOT #9** 2012-03-15 17:07**MOT test number** 198355472444**Result** ✓ Passed

**MOT #8**

2011-02-23 08:34

MOT test number

898934751031

Result

✓ Passed

- Notice** Front power steering pipe slightly corroded
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Inner Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #7

2011-02-18 11:19

MOT test number

355119941093

Result

✗ Failed

- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Inner Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Notice** Front power steering pipe slightly corroded
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Parking brake lever has no reserve travel (3.1.6b)

**MOT #6** 2010-03-08 15:58**MOT test number** 971497360006**Result** ✓ Passed**MOT #5** 2010-03-01 11:06**MOT test number** 734380660007**Result** ✗ Failed

- Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Fail** Brake pipe excessively corroded (3.6.B.2c)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

MOT #4 2009-03-02 15:27**MOT test number** 644031269038**Result** ✓ Passed

- Notice** Rear diff oil seal leaking

MOT #3 2008-02-22 12:22**MOT test number** 933513558059**Result** ✓ Passed



| | |
|-----------------|---|
| MOT #2 | 2007-03-08 11:27 |
| MOT test number | 201857167076 |
| Result | ✓ Passed |
| Advice | Brake disc slightly pitted (3.5.1h) |
| Advice | Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2) |
| Notice | Long travel noted at handbrake lever |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #1 | 2006-03-06 14:36 |
| MOT test number | 803385966077 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 April 2025

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 2 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 25 |
| First mileage registration | 2001-09-07 |
| Last registration | 2024-04-03 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2001-09-07 | 12 mi |
| Registration #2 | 2006-03-06 | 25.092 mi |
| Registration #3 | 2007-03-08 | 27.692 mi |
| Registration #4 | 2008-02-22 | 38.179 mi |
| Registration #5 | 2009-03-02 | 48.916 mi |
| Registration #6 | 2010-03-01 | 61.113 mi |
| Registration #7 | 2010-03-08 | 61.270 mi |
| Registration #8 | 2011-02-18 | 69.099 mi |
| Registration #9 | 2011-02-23 | 69.100 mi |
| Registration #10 | 2012-03-15 | 74.331 mi |
| Registration #11 | 2013-03-08 | 79.230 mi |
| Registration #12 | 2014-07-01 | 83.652 mi |
| Registration #13 | 2014-07-03 | 83.652 mi |
| Registration #14 | 2015-05-20 | 85.377 mi |
| Registration #15 | 2016-05-20 | 85.377 mi |
| Registration #16 | 2017-05-20 | 85.377 mi |
| Registration #17 | 2018-05-20 | 85.377 mi |
| Registration #18 | 2019-05-20 | 85.377 mi |
| Registration #19 | 2020-05-20 | 85.377 mi |
| Registration #20 | 2021-05-20 | 85.377 mi |
| Registration #21 | 2022-05-20 | 85.377 mi |
| Registration #22 | 2023-05-20 | 85.377 mi |
| Registration #23 | 2024-05-20 | 85.377 mi |
| Registration #24 | 2025-05-20 | 85.377 mi |
| Registration #25 | 2026-05-20 | 85.377 mi |



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|-------------|---------|
| Width | 1940 mm |
| Height | 1890 mm |
| Length | 4890 mm |
| Wheel base | 2850 mm |
| Kerb weight | 2465 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 96 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Engine number | 2UZ9028980 |