




General information

Make	ABARTH
Model	GRANDE PUNTO 155 BHP ABARTH
Colour	White
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Torque	201 Nm at 5.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.5 mpg
Consumption extra urban	44.4 mpg
Consumption combined	34.1 mpg
CO2 emission	162 g/km
CO2 label	G







Internet history

Advert 1

Date	2021-06-25
Pictures	29
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-04-10
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	26
Total items failed	21

MOT #20 2022-04-11 10:43

MOT test number 391847343253

Result ✔ Passed

Next expiry date 2023-04-10

Advice Exhaust noisy (8.1.1 (a))

Advice Exhaust has been modified

**MOT #19**

2022-03-31 10:01

MOT test number

346418878243

Result

✗ Failed

Fail Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Fail** Offside Rear Brake cable insecure (1.1.15 (c))**Advice** Exhaust noisy (8.1.1 (a))**Advice** Exhaust has been modified**Fail** Nearside Headlamp insecure (4.1.1 (c))**Fail** Offside Headlamp insecure (4.1.1 (c))**Fail** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Front Sub-frame corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**MOT #18**

2021-05-22 10:56

MOT test number

196569538150

Result

✓ Passed

MOT #17

2020-07-20 08:45

MOT test number

345050037618

Result

✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Registration plate insecure but not likely to fall off front lose but secure (0.1 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened rear disc pitted (1.1.14 (a) (ii))**Advice** Front front springs not fully mounted properly**Advice** Offside Rear Nail in tyre



MOT #16 2020-07-20 08:45

MOT test number 295756139225

Result ✗ Failed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Registration plate insecure but not likely to fall off front lose but secure (0.1 (a))

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened rear disc pitted (1.1.14 (a) (ii))

Advice Front front springs not fully mounted properly

Advice Offside Rear Nail in tyre

MOT #15 2019-07-22 10:51

MOT test number 830293972960

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2019-07-20 13:17

MOT test number 531293544619

Result ✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #13 2018-08-03 12:02

MOT test number 627408242537

Result ✓ Passed



MOT #12 2018-08-01 13:14

MOT test number 434514540680

Result ✔ Passed

MOT #11 2018-08-01 13:14

MOT test number 605618585121

Result ✘ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10 2017-06-01 10:11

MOT test number 930248736295

Result ✔ Passed

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

MOT #9 2017-05-31 08:44

MOT test number 339090365538

Result ✘ Failed

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Fail Nearside Front coil spring broken (2.4.C.1a)

MOT #8 2016-05-31 11:09

MOT test number 744950167274

Result ✔ Passed

Advice Rear Strong advise exhaust back box is badly corroded and outer covering breaking away from box

Advice Rear coil spring corroded nearside and offside coil springs corroded (2.4.C.1b)



MOT #7 2015-06-03 13:43

MOT test number 277464255103

Result ✓ Passed

- Advice** Rear coil spring corroded (2.4.C.1b)
- Notice** Rear exhaust back box is corroded and deteriorated

MOT #6 2015-05-26 11:12

MOT test number 749996845135

Result ✗ Failed

- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Front Coil spring not correctly located (2.4.C.2)
- Fail** Offside Front Coil spring not correctly located (2.4.C.2)
- Advice** Rear coil spring corroded (2.4.C.1b)
- Notice** Rear exhaust back box is corroded and deteriorated

MOT #5 2014-05-30 16:41

MOT test number 578640554170

Result ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Items removed from driver's view prior to test

MOT #4 2013-05-31 10:47

MOT test number 365741153111

Result ✓ Passed



MOT #3 2012-05-30 13:44

MOT test number 959111652146

Result ✓ Passed

MOT #2 2011-11-18 09:49

MOT test number 517972421352

Result ✓ Passed

MOT #1 2011-11-18 09:49

MOT test number 166172421352

Result ✗ Failed

Pass with rectification Nearside Front Headlamp aim too high (1.8)

Pass with rectification Offside Front Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 Juli 2023

✓
MOT
Expires:
10 April 2023

Tax status	Valid until 1 Juli
Days left	321
MOT expiry date	10 April 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 210,00,-
Single six month payment	£ 110,25,-
Total payable by 12 monthly instalments	£ 220,50,-




Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

Download >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

Download >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	RK58LAK
Plate since	2019-09-29
Current registration	RK58LAK
Plate since	2019-09-29

Download >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

Download >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-11-25
Last registration	2022-04-11
Complete history	See info



Registration #1	2008-11-25	26 mi
Registration #2	2011-11-18	20.064 mi
Registration #3	2012-05-30	23.773 mi
Registration #4	2013-05-31	31.192 mi
Registration #5	2014-05-30	37.400 mi
Registration #6	2015-05-26	44.395 mi
Registration #7	2015-06-03	44.781 mi
Registration #8	2016-05-31	55.140 mi
Registration #9	2017-05-31	68.324 mi
Registration #10	2017-06-01	68.324 mi
Registration #11	2018-08-01	80.796 mi
Registration #12	2019-05-31	91.277 mi
Registration #13	2019-05-31	91.277 mi
Registration #14	2019-05-31	91.277 mi
Registration #15	2019-05-31	91.277 mi
Registration #16	2019-05-31	91.277 mi
Registration #17	2019-05-31	91.277 mi
Registration #18	2019-05-31	91.277 mi
Registration #19	2019-05-31	91.277 mi
Registration #20	2019-05-31	91.277 mi
Registration #21	2022-04-11	91.277 mi

Download >



Premium report

Get the ABARTH premium report and get full access to more information.

- ✓ Finance check
- ✓ Mileage registrations (21)
- ✓ Damage check
- ✓ Stolen check
- ✓ Car features list
- ✓ Owners history + plate changes

[Download >](#)

Dimensions & weight

Width	1726 mm
Height	1490 mm
Length	4041 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine code	1308914