



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2009
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	196 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	12
Total items failed	3

MOT #16	2023-09-27 11:41
MOT test number	808590471880
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Rear Road wheel slightly distorted nearside and offside (5.2.2 (c) (i))

MOT #15	2023-09-27 09:12
MOT test number	329688613905
Result	✗ Failed
Advice	Rear Road wheel slightly distorted nearside and offside (5.2.2 (c) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing outer sidewall/inner edge worn (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing outer edge worn (5.2.3 (d) (ii))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing inner edge worn (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2022-09-28 08:34**MOT test number** 872878120991**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2021-10-05 14:15**MOT test number** 126474065821**Result** ✓ Passed**MOT #12** 2021-10-05 11:04**MOT test number** 546423103305**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2020-11-16 13:05**MOT test number** 564275589960**Result** ✓ Passed**MOT #10** 2019-11-15 10:13**MOT test number** 901843436523**Result** ✓ Passed**MOT #9** 2019-11-13 14:14**MOT test number** 423685169404**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #8** 2018-11-05 12:45**MOT test number** 658632050421**Result** ✓ Passed**MOT #7** 2017-10-27 11:35**MOT test number** 870490080411**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit also cracking on inner side wall (4.1.E.1)**MOT #6** 2016-10-25 13:57**MOT test number** 241612235035**Result** ✓ Passed**MOT #5** 2015-10-23 11:12**MOT test number** 735208166929**Result** ✓ Passed**MOT #4** 2014-11-03 13:29**MOT test number** 927007704394**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2013-11-21 11:19**MOT test number** 436115023353**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2013-09-30 10:14**MOT test number** 249283473257**Result** ✓ Passed



MOT #1	2012-09-24 14:12
MOT test number	379688862454
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KV59LJZ
Plate since	2019-06-29
Current registration	 KV59LJZ
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-22
Last registration	2023-09-27
Complete history	See info



Registration #1	2009-09-22	10 mi
Registration #2	2012-09-24	13.792 mi
Registration #3	2013-09-30	17.411 mi
Registration #4	2013-11-21	17.647 mi
Registration #5	2014-11-03	18.327 mi
Registration #6	2015-10-23	19.481 mi
Registration #7	2016-10-25	20.968 mi
Registration #8	2017-10-27	22.634 mi
Registration #9	2018-11-05	26.744 mi
Registration #10	2019-09-22	28.377 mi
Registration #11	2019-09-22	28.377 mi
Registration #12	2019-09-22	28.377 mi
Registration #13	2019-09-22	28.377 mi
Registration #14	2019-09-22	28.377 mi
Registration #15	2019-09-22	28.377 mi
Registration #16	2019-09-22	28.377 mi
Registration #17	2019-09-22	28.377 mi
Registration #18	2019-09-22	28.377 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431253706