



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK220 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	183 g/km
CO2 label	I







Internet history

Entry 1

Date	2022-02-03
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

**MOT expiry date** 2023-07-20**MOT pass rate** 93 %**MOT passed** 13**Failed MOT tests** 1**Total advice items** 15**Total items failed** 6**MOT #14** 2023-07-18 10:30**MOT test number** 500973975018**Result** ✗ Failed**Advice** Brake disc worn, but not excessively Both front's (1.1.14 (a) (i))**Fail** Exhaust emissions exceed level of metered smoke for a non-turbo charged engine (8.2.2.2 (b))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Headlamp aim unable to be tested (4.1.2 (b))**Advice** Nearside Front Road wheel slightly distorted Inner rim (5.2.2 (c) (i))**Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil Leak**MOT #13** 2022-07-18 11:04**MOT test number** 176659775889**Result** ✓ Passed

**MOT #12** 2021-07-21 15:49**MOT test number** 944231980787**Result** ✓ Passed**MOT #11** 2020-12-10 11:35**MOT test number** 249747641329**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10** 2019-12-06 09:58**MOT test number** 928670989372**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9** 2018-12-04 11:32**MOT test number** 569886138242**Result** ✓ Passed**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #8** 2017-12-04 13:11**MOT test number** 328786427465**Result** ✓ Passed**MOT #7** 2016-12-09 14:00**MOT test number** 786182725912**Result** ✓ Passed**Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)

**MOT #6** 2015-12-10 10:22**MOT test number** 821541579974**Result** ✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement tca (2.4.G.2)

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement tca (2.4.G.2)

**MOT #5** 2014-12-12 09:21**MOT test number** 557146244374**Result** ✓ Passed

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2014-03-07 13:51**MOT test number** 396166664009**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2013-03-19 15:26**MOT test number** 236988673039**Result** ✓ Passed**MOT #2** 2012-03-13 12:18**MOT test number** 368713972079**Result** ✓ Passed



MOT #1	2012-02-22 17:07
MOT test number	848023852037
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>KN09APX</b>
Plate since	2019-06-29
Current registration	<b>KN09APX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-20
Last registration	2023-07-18
Complete history	<a href="#">See info</a>



Registration #1	2009-03-20	27 mi
Registration #2	2012-02-22	20.698 mi
Registration #3	2012-03-13	20.715 mi
Registration #4	2013-03-19	24.778 mi
Registration #5	2014-03-07	31.257 mi
Registration #6	2014-12-12	33.848 mi
Registration #7	2015-12-10	52.172 mi
Registration #8	2016-12-09	65.889 mi
Registration #9	2017-05-22	75.277 mi
Registration #10	2017-05-22	75.277 mi
Registration #11	2017-05-22	75.277 mi
Registration #12	2017-05-22	75.277 mi
Registration #13	2017-05-22	75.277 mi
Registration #14	2017-05-22	75.277 mi
Registration #15	2017-05-22	75.277 mi
Registration #16	2017-05-22	75.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630637445