



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	BIPPER HDI TEPEE OUTDOOR
Colour	Grey
Year of manufacture	2012
Top speed	96 mph
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B





## MOT history

MOT expiry date	2021-03-01
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #8	2020-02-22 13:23
MOT test number	788804129256
Result	✓ Passed
Next expiry date	2021-03-01
Advice	Tyre worn close to legal limit/worn on edge both front wearing on edge's (5.2.3 (e))
Advice	Tyre slightly damaged/cracking or perishing both rear slight cracking (5.2.3 (d) (ii))

MOT #7	2019-02-23 11:22
MOT test number	983097251794
Result	✓ Passed

MOT #6	2018-02-17 10:27
MOT test number	398418155624
Result	✓ Passed
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Front Tyre worn close to the legal limit both tyres inner edge (4.1.E.1)

**MOT #5** 2017-03-02 15:04**MOT test number** 946532003156**Result** ✓ Passed**Advice** Both rear tyre wall perished.**MOT #4** 2017-02-27 11:47**MOT test number** 625577202909**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Both rear tyre wall perished.**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2016-01-25 18:57**MOT test number** 862590411871**Result** ✓ Passed**MOT #2** 2015-02-04 12:17**MOT test number** 439135835078**Result** ✓ Passed**Notice** N/s/f rim slightly damaged**Notice** Nail in offside rear tyre



MOT #1	2015-02-04 12:17
MOT test number	178325435000
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Notice	N/s/f rim slightly damaged
Notice	Nail in offside rear tyre



Tax & MOT check

X

Untaxed

Tax expired:  
17 February 2021

X

MOT

Expired:  
1 March 2021

Tax status	Expired at 17 February 2021
Days left	1168 days too late
MOT expiry date	1 March 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>RF61HZU</b>
Plate since	2024-03-29
Current registration	<b>RF61HZU</b>
Plate since	2024-03-29

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2012-02-22
Last registration	2020-02-22
Complete history	<a href="#">See info</a>



Registration #1	2012-02-22	19 mi
Registration #2	2015-02-04	14.517 mi
Registration #3	2016-01-25	22.686 mi
Registration #4	2017-02-27	29.094 mi
Registration #5	2018-02-22	35.502 mi
Registration #6	2019-02-22	41.910 mi
Registration #7	2020-02-22	48.318 mi
Registration #8	2021-02-22	54.726 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Wheel base	2513 mm
Kerb weight	1330 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	00014542232