





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	107 URBAN
Colour	Red
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg



CarCheck.co.uk page 1/11



YX08WJN

report date: 2024-03-28

# MOT history

MOT #12		2020-02-20 09:48
MOT test	number	132874440728
Result		✓ Passed
Next exp	iry date	2021-03-19
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear	(1.1.11 (c))
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rea	r (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #11		2019-02-22 14:58
MOT test	number	693207233032
Result		✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)	))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	c))

CarCheck.co.uk page 2/11



**MOT #10** 2019-02-22 14:39

**MOT test number** 648187950329

Result X Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Fail Central Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Fail

Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #9 2018-02-28 12:38

**MOT test number** 595257009161

Result \( \sqrt{Passed} \)

Advice Rear Rear brakes slightly binding

MOT #8 2017-03-01 12:20

**MOT test number** 559346019101

Result 

Passed

Advice Nearside Rear Brake Binding

**MOT #7** 2016-02-26 12:23

MOT test number 513508241597

**Result** 
✓ Passed

CarCheck.co.uk page 3/11



Result

Result

Advice

YX08WJN

report date: 2024-03-28

Passed

✓ Passed

MOT #6 2016-02-26 11:20

**MOT test number** 815243282191

Result X Failed

Fail Front Brakes imbalanced across an axle 32% (3.7.B.5b)

MOT #5 2015-03-03 12:27

**MOT test number** 968602165016

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

requires adjustment or repair. (3.7.B.5b)

**MOT #4** 2014-02-24 10:32

**MOT test number** 968485954024

MOT #3 2013-02-27 15:20

**MOT test number** 929578753054

**Notice** Offside rear tyre cracking in tread

**Notice** Nearside rear tyre cracking in tread

MOT #2 2012-03-05 15:10

MOT test number 215275462071

Result 

Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/11



MOT #1

MOT test number

Result

Notice N/s/r tyre has a nail in close to tyre wall may repaire or replace

2011-03-12 10:18

107051271417

✓ Passed

CarCheck.co.uk page 5/11



YX08WJN

report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner History		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		ОТ
**************************************		
***************************************		
***************************************		
********		
***************************************		
	More info >	
Plate changes  See in this check if this PEUGEOT had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since	PRO-2	1 10
Current registration	NK NK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-03-19
Last registration	2020-02-20
Complete history	See info



Registration #1	2008-03-19	25 mi
Registration #2	2011-03-12	11.338 mi
Registration #3	2012-03-05	17.585 mi
Registration #4	2013-02-27	24.505 mi
Registration #5	2014-02-24	27.384 mi
Registration #6	2015-03-03	30.790 mi
Registration #7	2016-02-26	34.783 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	790 kg
Max. allowed weight	1180 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	5789733

CarCheck.co.uk page 11/11