



MT59NLR

report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 I ROADSTER SE
Colour	Blue
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	167 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2023-10-02
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	30
Total items failed	1

MOT #11	2022-10-03 12:57
MOT test number	196819792932
Result	✓ Passed
Next expiry date	2023-10-02

MOT #10	2021-02-04 14:40
MOT test number	391967954317
Result	✓ Passed



MOT #9

2019-12-19 16:36

MOT test number

895660822336

Result

✓ Passed

- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Plastic covers fitted restricting full visual inspection
- Advice

Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))
- Advice

Corrosion starting on all steel suspension parts
- Advice

Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear of wheel both sides (5.3.4 (a) (i))
- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Rear Suspension rod corroded but not seriously weakened all (5.3.3 (b) (i))
- Advice

Offside Front Lower sound proofing around front cat security at rear most
- Advice

Rear Service brake binding but not excessively both sides (1.2.1 (f))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))



MOT #8	2018-12-19 13:43
MOT test number	936660815446
Result	✓ Passed
Advice	Brake hose slightly deteriorated all (1.1.12 (b) (ii))
Advice	Nearside Rear brake binding slightly
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
Advice	Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Plastic covers fitted restricting full visual inspection
Advice	General corrosion starting on all suspension parts
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #7** 2018-12-19 13:43**MOT test number** 158774921354**Result** ✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear brake binding slightly
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Brake hose slightly deteriorated all (1.1.12 (b) (ii))
- Advice** Plastic covers fitted restricting full visual inspection
- Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** General corrosion starting on all suspension parts

MOT #6 2017-12-11 08:47**MOT test number** 454391925460**Result** ✓ Passed**MOT #5** 2017-01-06 13:44**MOT test number** 676823248714**Result** ✓ Passed**MOT #4** 2016-01-08 10:23**MOT test number** 418255463051**Result** ✓ Passed



MOT #3	2014-12-10 10:53
MOT test number	399534944321
Result	✓ Passed

MOT #2	2013-12-07 11:05
MOT test number	196691943396
Result	✓ Passed
Advice	Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Rear Shock absorber has a light misting of oil (2.7.3)

MOT #1	2012-12-01 10:26
MOT test number	475386232411
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-12-16
Last registration	2022-10-03
Complete history	See info



Registration #1	2009-12-16	13 mi
Registration #2	2012-12-01	53.866 mi
Registration #3	2013-12-07	69.638 mi
Registration #4	2014-12-10	75.074 mi
Registration #5	2016-01-08	78.765 mi
Registration #6	2017-01-06	82.764 mi
Registration #7	2017-12-11	88.653 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	4020 mm
Wheel base	2330 mm
Kerb weight	1155 kg
Max. allowed weight	1375 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	L8 20275104