



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D DRIVE R-DESIGN
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-16
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-16
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	24
Total items failed	1

MOT #13	2024-01-16 14:37
MOT test number	893785155898
Result	✓ Passed
Next expiry date	2025-01-16
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Tyre 1.6mm + devoid of tread on inner edge (5.2.3 (e))

MOT #12	2024-01-16 14:37
MOT test number	693055213307
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Tyre 1.6mm + devoid of tread on inner edge (5.2.3 (e))

MOT #11	2022-12-19 12:22
MOT test number	177321049972
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm + devoid of tread on inner edge (5.2.3 (e))
Advice	Direction indicator slightly discoloured Both rear (4.4.3 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm + devoid of tread on inner edge (5.2.3 (e))

**MOT #10** 2022-01-17 18:47**MOT test number** 642602652647**Result** ✓ Passed**MOT #9** 2021-10-27 08:49**MOT test number** 544190927830**Result** ✓ Passed

- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
- Advice** Tyres slightly distorted
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Washers weak

MOT #8 2020-11-16 12:07**MOT test number** 466203287778**Result** ✓ Passed

- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #7 2019-11-15 14:55**MOT test number** 990174370273**Result** ✓ Passed

- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #6** 2018-10-25 12:31**MOT test number** 751835238880**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Rear tyres distorted**MOT #5** 2017-10-31 16:02**MOT test number** 577931168922**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)**Advice** Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2016-11-16 16:39**MOT test number** 222315527155**Result** ✓ Passed**MOT #3** 2015-11-18 11:48**MOT test number** 550712635444**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)



MOT #2	2014-11-12 11:49
MOT test number	657326614394
Result	✓ Passed
Advice	Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1	2013-07-10 09:33
MOT test number	695111693133
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
16 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-30
Last registration	2024-01-16
Complete history	See info



Registration #1	2010-06-30	19 mi
Registration #2	2013-07-10	54.632 mi
Registration #3	2014-11-12	76.580 mi
Registration #4	2015-11-18	90.963 mi
Registration #5	2016-11-16	107.163 mi
Registration #6	2017-10-31	116.658 mi
Registration #7	2018-10-25	127.590 mi
Registration #8	2019-11-15	135.057 mi
Registration #9	2020-05-20	151.277 mi
Registration #10	2021-05-20	161.277 mi
Registration #11	2022-05-20	171.277 mi
Registration #12	2023-05-20	181.277 mi
Registration #13	2024-01-16	191.277 mi
Registration #14	2024-01-16	191.277 mi
Registration #15	2024-01-16	191.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553