





General information

Make	MERCEDES
Model	A-CLASS A160 AVANTGARDE
Colour	Silver
Year of manufacture	2000
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	102 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.7 mpg





Internet history

Entry 2		
Date	2021-10-23	
Pictures	6	
Listing price	View report	




source: autotrader.co.uk

Entry 1	
Date	2021-06-15
Pictures	6
Listing price	<u>View report</u>



source: autotrader.co.uk









MOT history

MOT expiry date	2024-06-30
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	7
Total items failed	3

MOT #11	2023-06-23 14:06
MOT test number	700088707153
Result	✓ Passed
Next expiry date	2024-06-30
Advice Nearside Front Suspension arm pin or bush worn but not resulting in e (a) (i))	xcessive movement (5.3.4

MOT #10	2023-06-23 11	:54
MOT test	number 6371398684	178
Result	🗙 Fai	led
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords	
205/45r16 (5.2.3 (d) (i))		
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4	

MOT #9		2022-07-01 15:10
MOT test number		716561121042
Result		✓ Passed
Advice Nearside Front Su (a) (i))	spension arm pin or bush worn b	ut not resulting in excessive movement (5.3.4





MOT #8		2022-06-29 14:50
MOT test	number	873765127048
Result		🗙 Failed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exce	ssive movement (5.3.4
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
MOT #7		2021-05-17 13:40
MOT test number 555392172355		
Result V Passed		✓ Passed

.....

МОТ #6	2020-06-30 10:07
MOT test number	126563410178
Result	✓ Passed

MOT #5	2008-07-07 15:25
MOT test number	674139488167
Result	✓ Passed

МОТ #4	2008-07-03 14:32
MOT test number	243975288457
Result	🗙 Failed
Fail Nearside Registration plate lamp not working (1.1.5c)	
Fail Nearside Rear Radius arm has excessive play in a pin/bearing (2.4.G.2)	

MOT #3	2007-07-23 12:51
MOT test number	764144207270
Result	✓ Passed



X162	YAP
report date:	2024-03-29

MOT #2	2006-08-16 12:24
MOT test number	424088926225
Result	✓ Passed
MOT #1	2006-08-16 09:18
MOT test number	392338826417
Result	🗙 Failed
Fail Offside Rear coil spring fractured (2.4.C.1a)	



Tax & MOT check







Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	AMP
Туре	A CONTRACT
Damage 2	AMPLE
Damaye z	E CAT D
Date	
Category	AMPT
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



X162YAP report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2000-09-28
Last registration	2023-06-23
Complete history	See info



Registration #1	2000-09-28	8 mi
Registration #2	2006-08-16	28.722 mi
Registration #3	2006-08-16	28.722 mi
Registration #4	2007-07-23	28.941 mi
Registration #5	2008-07-03	3.412 mi
Registration #6	2008-07-07	34.154 mi
Registration #7	2020-06-30	36.174 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		10.200 est



X162YAP report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1941 mm
Height	1575 mm
Length	3575 mm
Wheel base	2432 mm
Kerb weight	1040 kg
Additional information	
Fuel tank capacity	54 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2