



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE TDI 105BHP
Colour	Beige
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-04
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-28
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	37
Total items failed	5

MOT #15	2024-03-01 17:10
MOT test number	738352262219
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2024-02-20 11:58
MOT test number	721544919653
Result	✗ Failed
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
Fail	Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill has hole (7.1.1 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt

**MOT #13**

2023-02-15 08:47

MOT test number

825679175239

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12**

2022-02-22 13:10

MOT test number

831491523246

Result

✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Exhaust mounting defective back box corroded (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11**

2022-02-22 13:10

MOT test number

158565697079

Result

✗ Failed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Exhaust mounting defective back box corroded (6.1.2 (a))**Pass with rectification** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #10** 2021-01-13 09:01**MOT test number** 934470949757**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #9** 2020-01-09 09:12**MOT test number** 666140191868**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8** 2019-01-05 10:17**MOT test number** 375783701227**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2018-02-01 11:46**MOT test number** 905825907562**Result** ✓ Passed**MOT #6** 2018-02-01 09:33**MOT test number** 994902064995**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #5** 2017-03-02 11:58**MOT test number** 990362503508**Result** ✓ Passed**MOT #4** 2017-03-02 11:58**MOT test number** 853017051347**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2016-03-01 15:16**MOT test number** 496512697344**Result** ✓ Passed**Advice** Front brake fluctuating, but not excessively both sides (3.7.B.3)**Advice** Offside wiper blade torn slightly**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened pitted inner face (3.5.1i)**MOT #2** 2015-03-02 12:22**MOT test number** 609901765065**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Both front tyres worn on inner edge**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-03-04 10:28
MOT test number	766423464000
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
28 February 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GD11FHX
Plate since	2024-03-29
Current registration	 GD11FHX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-05
Last registration	2024-03-01
Complete history	See info



Registration #1	2011-03-05	22 mi
Registration #2	2014-03-04	30.757 mi
Registration #3	2015-03-02	39.905 mi
Registration #4	2016-03-01	46.309 mi
Registration #5	2017-03-02	50.110 mi
Registration #6	2017-03-02	50.110 mi
Registration #7	2018-02-01	53.781 mi
Registration #8	2018-02-01	53.781 mi
Registration #9	2019-01-05	63.259 mi
Registration #10	2019-01-05	63.259 mi
Registration #11	2019-01-05	63.259 mi
Registration #12	2019-01-05	63.259 mi
Registration #13	2019-01-05	63.259 mi
Registration #14	2019-01-05	63.259 mi
Registration #15	2019-01-05	63.259 mi
Registration #16	2019-01-05	63.259 mi
Registration #17	2019-01-05	63.259 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1460 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

BSW 022728