





report date: 2024-03-29

General information

Make	PEUGEOT
Model	5008 HDI ALLURE
Colour	Black
Year of manufacture	2013
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-07-15

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-24
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	20
Total items failed	1

MOT #11		2023-09-25 16:17
MOT test	number	350155876055
Result		✓ Passed
Next expi	ry date	2024-09-24
Advice Service brake efficiency only just met - rear efforts low		
Advice Nearside Front Suspension arm ball joint has slight play & offside front (5.3.4 (a) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on the inner shoulder (5.2.3 (e))		

MOT #10		2023-07-27 08:35
MOT test	number	303642191575
Result		× Failed
Advice	Items removed from driver's view prior to test	
Advice	Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
MAJOR	Windscreen washer not working (3.5 (a))	
Advice	Play in steering rack inner joint(s) Very slight both sides	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/12



KT13URG

report date: 2024-03-29

Passed

MOT #9 2022-07-07 15:40

MOT test number 444503197793

MOT #8 2022-07-07 13:59

MOT test number 420327892007

Result X Failed

MAJOR Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #7 2020-12-16 15:07

MOT test number 341187387901

Result \rightarrow Passed

MOT #6 2020-12-04 10:21

MOT test number 490773991867

Result X Failed

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Offside Headlamp aim projected beam image is obviously incorrect bulb in wrong? (4.1.2 (c))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #5 2019-05-29 14:16

MOT test number 606285099807

Advice Both rear tyre little low on tread

Result

CarCheck.co.uk page 4/12



Fail

KT13URG
report date: 2024-03-29

MOT test number

Result

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

MOT test number

Result

Advice Undertray fitted

Advice Front brake discs corroded and lipped

MOT #2

MOT test number

550867189050

Result

✓ Passed

MOT #1 2016-07-22 14:34 MOT test number 294970180541

Result X Failed

Offside Front Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 24 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-07-24
Last registration	2023-09-25
Complete history	See info



Registration #1	2013-07-24	21 mi
Registration #2	2016-07-22	38.432 mi
Registration #3	2016-07-23	38.432 mi
Registration #4	2017-06-07	39.525 mi
Registration #5	2018-05-16	49.370 mi
Registration #6	2019-05-29	60.407 mi
Registration #7	2020-12-04	69.718 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.074

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2728 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

Engine number JBER0097986