



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Blue
Year of manufacture	2006
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-01-11
Pictures	31
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-01-22
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	19
Total items failed	9

MOT #19	2021-12-30 16:06
MOT test number	976278769951
Result	✓ Passed
Next expiry date	2023-01-22
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #18	2021-12-29 10:23
MOT test number	825629553768
Result	✗ Failed
Fail	Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #17	2021-01-12 14:04
MOT test number	338051517537
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Outer Sill (5.3.6 (a) (i))

**MOT #16** 2020-01-09 15:20**MOT test number** 758131118603**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material All pipes (1.1.11 (c))**Advice** Coil spring corroded All have some corrosion (5.3.1 (b) (i))**MOT #15** 2019-01-09 17:05**MOT test number** 690980011253**Result** ✓ Passed**Advice** Both front wiper blade split**Advice** Light corrosion on nearside main brake pipe and offside rear brake pipe to the wheel cylinder**MOT #14** 2019-01-09 11:56**MOT test number** 805875296431**Result** ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Both front wiper blade split**Fail** Nearside Front Macpherson strut pin or bush excessively worn top mounting bush (5.3.4 (a) (i))**Fail** Front Exhaust has a major leak of exhaust gases flexible pipe (6.1.2 (a))**Advice** Light corrosion on nearside main brake pipe and offside rear brake pipe to the wheel cylinder**MOT #13** 2018-01-23 15:51**MOT test number** 539007572248**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #12** 2016-12-23 12:19**MOT test number** 904126336530**Result** ✓ Passed**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**MOT #11** 2016-12-22 11:14**MOT test number** 138093948441**Result** ✗ Failed**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Fail** Central Front Exhaust has a major leak of exhaust gases (7.1.2)**MOT #10** 2015-12-23 11:48**MOT test number** 880614937219**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-12-27 10:42**MOT test number** 345041264379**Result** ✓ Passed**MOT #8** 2014-12-27 10:42**MOT test number** 107061264342**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**MOT #7** 2013-12-27 11:35**MOT test number** 478151763466**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-10-24 10:20**MOT test number** 148918192272**Result** ✓ Passed**MOT #5** 2011-10-24 10:08**MOT test number** 306617491429**Result** ✓ Passed**MOT #4** 2010-10-20 11:44**MOT test number** 800483790201**Result** ✓ Passed**MOT #3** 2010-03-30 16:33**MOT test number** 802079580052**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-03-29 16:36**MOT test number** 501818880032**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2009-03-06 16:56
MOT test number	502345369045
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
3 January 2023

X

MOT

Expired:
22 January 2023

Tax status	Expired at 3 January 2023
Days left	482 days too late
MOT expiry date	22 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-23
Last registration	2021-12-30
Complete history	See info



Registration #1	2006-03-23	12 mi
Registration #2	2009-03-06	18.683 mi
Registration #3	2010-03-29	25.765 mi
Registration #4	2010-03-30	25.783 mi
Registration #5	2010-10-20	28.690 mi
Registration #6	2011-10-24	33.147 mi
Registration #7	2012-10-24	40.549 mi
Registration #8	2013-12-27	46.486 mi
Registration #9	2014-12-27	50.069 mi
Registration #10	2015-12-23	47.258 mi
Registration #11	2016-03-23	45.257 mi
Registration #12	2016-03-23	45.257 mi
Registration #13	2016-03-23	45.257 mi
Registration #14	2016-03-23	45.257 mi
Registration #15	2016-03-23	45.257 mi
Registration #16	2016-03-23	45.257 mi
Registration #17	2016-03-23	45.257 mi
Registration #18	2016-03-23	45.257 mi
Registration #19	2016-03-23	45.257 mi
Registration #20	2016-03-23	45.257 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG6096333