



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF GT TDI DSG
Colour	Grey
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F





## MOT history

MOT expiry date	2024-11-12
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	37
Total items failed	14

## MOT #16 2023-11-07 15:43

MOT test number 359120637990

Result ✓ Passed

Next expiry date 2024-11-12

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #15 2023-11-07 09:54

MOT test number 107953387852

Result ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

## MOT #14 2022-11-08 11:53

MOT test number 729084891819

Result ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement at rear (5.3.4 (a) (i))

**MOT #13** 2021-11-13 11:28**MOT test number** 248531327751**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-10-10 15:10**MOT test number** 740862599918**Result** ✓ Passed**Advice** Drivers door does not fully open**Advice** T.p.m.s lamp on**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front wing damaged**Advice** Rear bumper misaligned

**MOT #11**

2020-10-09 13:25

**MOT test number**

103889702350

**Result****✗ Failed**

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened badly scored (1.1.14 (a) (ii))

**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Brake pad warning lamp on

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Drivers door does not fully open

**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** T.p.m.s lamp on

**Fail** Offside Front Headlamp aim not tested (4.1.2 (b))

**Advice** Rear bumper misaligned

**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**Advice** Offside Front wing damaged

**MOT #10**

2019-04-03 11:26

**MOT test number**

150383045645

**Result****✓ Passed**

**Advice** Brake pad warning light on

**Advice** Nearside Front body panel damaged

**MOT #9** 2019-04-02 14:11**MOT test number** 267953146698**Result** ✗ Failed**Advice** Engine oil level low**Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges worn smooth (5.2.3 (e))**Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Emissions not tested exhaust leak and oil level low (8.2.2.2 (e))**Advice** Brake pad warning light on**Advice** Nearside Front body panel damaged**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #8** 2018-04-05 09:03**MOT test number** 608140373846**Result** ✓ Passed**Advice** Emissions not detected**Advice** Central Exhaust clamp broken**MOT #7** 2017-04-04 14:01**MOT test number** 144121548637**Result** ✓ Passed**MOT #6** 2017-04-04 12:21**MOT test number** 163761618333**Result** ✗ Failed**Fail** Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #5** 2016-04-07 12:42**MOT test number** 390709723930**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2015-04-01 13:12**MOT test number** 456351195089**Result** ✓ Passed**MOT #3** 2014-03-03 14:11**MOT test number** 748732264021**Result** ✓ Passed**Notice** Rear brake discs show substantial corrosion.**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Front brake discs show substantial corrosion.**Notice** Exhaust centre clamp is heavily deteriorated.**MOT #2** 2013-04-03 14:56**MOT test number** 895603993051**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** ALL Brake Discs slightly worn, with pitted edges.**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2011-12-12 14:15**MOT test number** 538936141356**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
12 November 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	12 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>AM58XYO</b>
Plate since	2024-03-29
Current registration	 <b>AM58XYO</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-01-02
Last registration	2023-11-07
Complete history	<a href="#">See info</a>



Registration #1	2009-01-02	25 mi
Registration #2	2011-12-12	37.689 mi
Registration #3	2013-04-03	49.236 mi
Registration #4	2014-03-03	57.014 mi
Registration #5	2015-04-01	66.117 mi
Registration #6	2016-04-07	74.607 mi
Registration #7	2017-04-04	95.990 mi
Registration #8	2017-04-04	95.990 mi
Registration #9	2018-04-05	107.356 mi
Registration #10	2019-04-05	118.722 mi
Registration #11	2020-04-05	130.088 mi
Registration #12	2021-04-05	141.454 mi
Registration #13	2022-04-05	152.820 mi
Registration #14	2023-04-05	164.186 mi
Registration #15	2023-11-07	175.552 mi
Registration #16	2023-11-07	175.552 mi
Registration #17	2023-11-07	175.552 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1322 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 657988