





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE SCENIC DYNAMIQUE DCI 106 SCENIC
Colour	Grey
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/14



FL57TFF

report date: 2024-03-29

Internet history

Entry 6


Date 2021-07-08

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 5

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 4

Date 2021-06-27

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-06-12

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk


Entry 1


Date 2021-0	6-05
-------------	------


Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-12
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	19
Total items failed	20

MOT #21		2023-11-04 12:43
MOT test	number	340379177197
Result		✓ Passed
Next expi	ry date	2024-11-12
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #20	2023-11-01 10:17
MOT test number	290508293002
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #19	2022-11-12 10:39
MOT test number	833981417419
Result	✓ Passed

CarCheck.co.uk page 3/14



MOT #18 2022-10-29 09:51

MOT test number 302372471593

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Outer Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #17 2021-11-09 13:25

MOT test number 936721625768

Result ✓ Passed

MOT #16 2021-10-30 09:19

MOT test number 812101416822

Result X Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #15 2020-10-30 13:19

MOT test number 534898391808

Result ✓ Passed

MOT #14 2019-10-21 11:06

MOT test number 397394886476

Result ✓ Passed

CarCheck.co.uk page 4/14



MOT #13 2018-11-13 14:36

MOT test number 242750215862

Result ✓ Passed

Advice

(3.5.1i)

Nearside MIRROR MISSING

MOT #12 2017-11-02 10:41

MOT test number 795022272055

Result ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened Slight, pads approx 60% worn

MOT #11 2017-11-01 12:39

MOT test number 675592803063

Result × Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Headlamp aim too high (1.8)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Offside Headlamp aim too high (1.8)

MOT #10 2017-04-27 12:31

MOT test number 440933255812

Result ✓ Passed

CarCheck.co.uk page 5/14



MOT #9 2017-04-27 12:31

MOT test number 708103221196

Result X Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #8 2016-05-06 09:28

MOT test number 936971295320

Result ✓ Passed

Advice Undertrays fitted obscuring some underside components

MOT #7 2016-05-06 09:28

MOT test number 728678921781

Result X Failed

Advice Undertrays fitted obscuring some underside components

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

MOT #6 2014-12-29 11:42

MOT test number 439443664414

Result
✓ Passed

MOT #5 2014-05-31 09:36

MOT test number 358051454188

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



FL57TFF

report date: 2024-03-29

MOT #4

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

635767551247

Result

Notice N/s/r light lens cracked

MOT test number

Fail Offside Front Steering pivot point has excessive play (2.2.B.1g)

Notice N/s/r light lens cracked

Fail Nearside Front Steering pivot point has excessive play (2.2.B.1g)

MOT test number

673733750289

Result

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Slight play in both front track rods

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



FL57TFF

report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2007-09-01
Last registration	2023-11-04
Complete history	See info



Registration #1	2007-09-01	27 mi
Registration #2	2010-09-10	22.250 mi
Registration #3	2011-09-14	32.014 mi
Registration #4	2011-09-14	32.014 mi
Registration #5	2012-09-18	42.093 mi
Registration #6	2014-05-31	55.998 mi
Registration #7	2014-12-29	58.202 mi
Registration #8	2016-05-06	66.564 mi
Registration #9	2016-05-06	66.564 mi
Registration #10	2017-04-27	72.740 mi
Registration #11	2017-04-27	72.740 mi
Registration #12	2017-11-01	74.733 mi
Registration #13	2017-11-02	74.733 mi
Registration #14	2018-11-13	91.283 mi
Registration #15		11.177 mi
Registration #16		11.117 ea
Registration #17		11.177 mi
Registration #18		11.117 ea
Registration #19		11.177 mi
Registration #20		11.117 ea
Registration #21		11.177 mi
Registration #22		11.177 ea
Registration #23		11.177 mi
Registration #24		11.117 es
Registration #25		11,177 es
Registration #26		11.117 es
CarCheck.co.uk		page 13/14

Registration #27

Registration #28

More info >

mn.n.n



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2087 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1200 kg
Max. allowed weight	1945 kg

Additional information

Fuel tank capacity	49	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 14/14