





report date: 2024-03-29

### General information

Make	FIAT
Model	FIORINO 16V MULTIJET ADVENTURE
Colour	Silver
Year of manufacture	2015
Top speed	97 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

## Entry 2

Date 2021-07-04

Pictures 45

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-03

Pictures 45

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-22
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	6
Total items failed	11

MOT #11	2023-08-22 08:41
MOT test number	221031759341
Result	<b>✓</b> Passed
Next expiry date	2024-08-22
Advice Temp repair os mirror	

MOT #10	2023-08-16 13:19	
MOT test number	251811452449	
Result	<b>X</b> Failed	
Fail Nearside Front Macpherson strut fractured (5.3.3 (b) (ii))  Advice Temp repair os mirror		
Fail Nearside Front Macpherson strut attachment bracket/mounting insecure and impairing directional		
stability strut top mount (5.3.3 (a) (ii))		

MOT #9	2022-08-23 11:49
MOT test number	524599162159
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2022-08-23 09:03

**MOT test number** 162709449147

Result X Failed

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #7 2021-06-21 07:01

**MOT test number** 350889617302

**Result** ✓ Passed

MOT #6 2021-06-15 12:57

**MOT test number** 206448233244

**Result** ★ Failed

Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

**Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

MOT #5 2020-10-12 09:56

**MOT test number** 626871649384

Result \rightarrow Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2020-10-12 09:56

**MOT test number** 954801882283

Result X Failed

Pass with rectification Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2019-10-18 07:54
MOT test number 470329455418

Result 

Passed

MOT #2 2019-10-17 12:07

MOT test number 149084503202

Result × Failed

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #1** 2018-10-17 11:00

**MOT test number** 503680967938

Result \( \sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	22 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \( \frac{1}{2} \)	
*********	
***************************************	
***************************************	
HEREETE STATE OF THE STATE OF T	
***************************************	
Plate changes	More info >
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	OK OK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-11-01
Last registration	2023-08-22
Complete history	See info



Registration #1	2015-11-01	8 mi
Registration #2	2018-10-17	48.680 mi
Registration #3	2019-10-17	66.723 mi
Registration #4	2019-10-18	66.723 mi
Registration #5	2020-10-12	76.559 mi
Registration #6	2020-10-12	76.559 mi
Registration #7	2021-06-15	83.253 mi
Registration #8		77.77
Registration #9		77.777 46
Registration #10		77.77
Registration #11		11.777 es
Registration #12		77,777 46
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

Dim	ensior	2 2	MOIO	hŧ
	ensioi	15 (2	werd	

Width	1716 mm
Height	1721 mm
Length	3864 mm
Wheel base	2513 mm
Kerb weight	1090 kg
Max. allowed weight	1750 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	5843290

CarCheck.co.uk page 12/12