



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA POP DUALOGIC
Colour	Yellow
Year of manufacture	2011
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	113 g/km
CO2 label	C





MOT history

MOT expiry date	2023-10-22
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	69
Total items failed	17

MOT #17	2024-03-14 11:21
---------	------------------

MOT test number	288071626844
-----------------	--------------

Result	✗ Failed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #16**

2024-02-29 11:21

MOT test number

846052265594

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength AXLE (5.3.6 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #15

2022-10-20 11:06

MOT test number

148913373306

Result**✓ Passed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Under-trays fitted obscuring some underside components
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2021-10-22 12:50

MOT test number

317894341569

Result

✓ Passed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 155/80/13 (5.2.3 (e))

MOT #13

2021-10-22 10:30

MOT test number

238550734175

Result

✗ Failed

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 155/80/13 (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

**MOT #12** 2020-10-20 15:06**MOT test number** 513655371770**Result** ✓ Passed**MOT #11** 2020-10-14 13:43**MOT test number** 479229568976**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**MOT #10** 2019-10-22 16:01**MOT test number** 562459099890**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** All four suspension coil springs corroded**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** All four road wheels corroded**Advice** Both front shock absorbers corroded

**MOT #9** 2019-10-21 15:50**MOT test number** 894423459437**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** All four road wheels corroded**Advice** Both front shock absorbers corroded**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** All four suspension coil springs corroded**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**MOT #8** 2018-10-23 07:56**MOT test number** 137190571192**Result** ✓ Passed**Advice** Exhaust tailbox deteriorated slightly**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #7** 2018-01-25 14:49**MOT test number** 401727107287**Result** ✓ Passed**Advice** Exhaust front pipe bracket corroded**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Front and rear exhaust clamps corroded**Advice** Exhaust tailbox deteriorated slightly

**MOT #6**

2018-01-24 14:04

MOT test number

271663669536

Result**✗ Failed****Advice** Front and rear exhaust clamps corroded**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Exhaust tailbox deteriorated slightly**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Exhaust front pipe bracket corroded**MOT #5**

2017-01-31 09:19

MOT test number

286693997463

Result**✓ Passed****Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Rear silencer slightly deteriorated**MOT #4**

2017-01-30 11:27

MOT test number

765150395784

Result**✗ Failed****Advice** Rear silencer slightly deteriorated**Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)**Fail** Nearside Rear Shock absorber has an excessively worn bush top bush (2.7.4)**Fail** Offside front brake excessively fluctuating badly pitted brake disc (3.7.B.3)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Fail** Offside Rear Shock absorber has an excessively worn bush top bush (2.7.4)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2016-02-01 09:45**MOT test number** 729383046431**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear exhaust box deteriorated**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-01-21 09:13**MOT test number** 247731125068**Result** ✓ Passed**Advice** Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Notice** Rear exhaust clamp corroded**Notice** N/s & o/s rear tyres perished between tread**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Exhaust tailbox slightly corroded**MOT #1** 2014-01-14 16:53**MOT test number** 485414914060**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
22 October 2023

Tax status	Expired at 1 March 2024
Days left	59 days too late
MOT expiry date	22 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-01-27
Last registration	2024-03-14
Complete history	See info



Registration #1	2011-01-27	26 mi
Registration #2	2014-01-14	14.227 mi
Registration #3	2015-01-21	17.683 mi
Registration #4	2016-02-01	20.730 mi
Registration #5	2017-01-30	22.627 mi
Registration #6	2017-01-31	22.628 mi
Registration #7	2018-01-24	23.061 mi
Registration #8	2018-01-25	23.061 mi
Registration #9	2018-10-23	24.972 mi
Registration #10	2019-01-27	25.377 mi
Registration #11	2019-01-27	25.377 mi
Registration #12	2019-01-27	25.377 mi
Registration #13	2019-01-27	25.377 mi
Registration #14	2019-01-27	25.377 mi
Registration #15	2019-01-27	25.377 mi
Registration #16	2019-01-27	25.377 mi
Registration #17	2019-01-27	25.377 mi
Registration #18	2019-01-27	25.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6491843