



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	ACCENT GSI
Colour	Gold
Year of manufacture	-
Top speed	105 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	114 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-07-14
Pictures	33
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-30
Pictures	33
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT #21	2022-10-11 09:38
---------	------------------

MOT test number	993916278413
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-10-11
------------------	------------

- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 185/60r14 (5.2.3 (d) (ii))

MOT #20	2022-09-30 10:59
---------	------------------

MOT test number	112344262052
-----------------	--------------

Result	✗ Failed
--------	----------

**Advice** Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement Both inner bushes worn. (5.3.4 (a) (i))

**Advice** Rear Tyre slightly damaged/cracking or perishing Both tyres cracking in tread. (5.2.3 (d) (ii))

**Fail** Central Front Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

**Advice** Offside Rear Exhaust mounting defective Silencer 1/2 Mounting broken. (6.1.2 (a))

**Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced Wheel arch corroded. (6.1.1 (c) (i))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Fail** Front Headlamp has a product on the lens so that the light output is severely reduced Both Headlamps. (4.1.4 (b))



<b>MOT #19</b>	2021-10-02 14:57
<b>MOT test number</b>	126713775715
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

<b>MOT #18</b>	2020-10-02 15:36
<b>MOT test number</b>	317108583617
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Exhaust mounting defective (6.1.2 (a))
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Centre stop light not working.
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #17</b>	2020-10-02 15:36
<b>MOT test number</b>	465707656033
<b>Result</b>	✗ Failed
<b>Advice</b>	Rear Exhaust mounting defective (6.1.2 (a))
<b>Advice</b>	Centre stop light not working.
<b>Advice</b>	Rear Child Seat fitted not allowing full inspection of adult belt
<b>Pass with rectification</b>	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Pass with rectification</b>	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Pass with rectification</b>	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #16** 2019-10-02 10:20**MOT test number** 867438299482**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2019-10-01 16:13**MOT test number** 210519589938**Result** ✗ Failed**Fail** Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))**MOT #14** 2018-10-12 09:08**MOT test number** 817694721546**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake pad(s) wearing thin 2MM (1.1.13 (a) (ii))

**MOT #13**

2018-10-11 16:32

**MOT test number**

713377753238

**Result****✗ Failed**

- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Rear Exhaust system insecure BOX (6.1.2 (a))
- Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin 2MM (1.1.13 (a) (ii))

**MOT #12**

2017-09-22 10:07

**MOT test number**

829113468921

**Result****✓ Passed**

- Advice** Nearside Headlamp deteriorated but light output not reduced lens stained (1.7.5a)
- Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** High level stop lamp not working
- Advice** Offside Headlamp deteriorated but light output not reduced lens stained (1.7.5a)
- Advice** Engine oil level low
- Advice** Exhaust has a minor leak of exhaust gases downpipe (7.1.2)



MOT #11	2017-09-18 11:53
MOT test number	301168727441
Result	✗ Failed
Advice	High level stop lamp not working
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Advice	Offside Headlamp deteriorated but light output not reduced lens stained (1.7.5a)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Exhaust has a minor leak of exhaust gases downpipe (7.1.2)
Advice	Engine oil level low
Advice	Nearside Headlamp deteriorated but light output not reduced lens stained (1.7.5a)
Advice	Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #10	2016-09-30 10:21
MOT test number	434509705621
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Engine oil level low
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	High level stop lamp not working
Advice	Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)



**MOT #9** 2016-09-30 10:21**MOT test number** 858187568471**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Engine oil level low**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** High level stop lamp not working**MOT #8** 2015-10-05 14:00**MOT test number** 398670829871**Result** ✓ Passed**MOT #7** 2015-10-02 10:54**MOT test number** 367162491537**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #6** 2014-10-03 14:00**MOT test number** 139126974293**Result** ✓ Passed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #5** 2014-10-03 13:07**MOT test number** 687326974295**Result** ✗ Failed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2013-10-03 14:43**MOT test number** 217676773271**Result** ✓ Passed**MOT #3** 2011-03-24 11:47**MOT test number** 907763181015**Result** ✓ Passed**MOT #2** 2011-03-24 11:44**MOT test number** 825733181026**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2008-01-14 10:55**MOT test number** 254724818083**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2023-03-28
Current registration	 
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-11-29
Last registration	2022-10-11
Complete history	<a href="#">See info</a>



Registration #1	2004-11-29	8 mi
Registration #2	2008-01-14	54.492 mi
Registration #3	2011-03-24	54.522 mi
Registration #4	2011-03-24	54.522 mi
Registration #5	2013-10-03	54.818 mi
Registration #6	2014-10-03	57.913 mi
Registration #7	2014-10-03	57.913 mi
Registration #8	2015-10-02	63.217 mi
Registration #9	2015-10-05	63.217 mi
Registration #10	2016-09-30	67.703 mi
Registration #11	2016-09-30	67.703 mi
Registration #12	2017-09-18	73.450 mi
Registration #13	2018-09-18	73.450 mi
Registration #14	2018-09-18	73.450 mi
Registration #15	2018-09-18	73.450 mi
Registration #16	2018-09-18	73.450 mi
Registration #17	2018-09-18	73.450 mi
Registration #18	2018-09-18	73.450 mi
Registration #19	2018-09-18	73.450 mi
Registration #20	2018-09-18	73.450 mi
Registration #21	2018-09-18	73.450 mi
Registration #22	2018-09-18	73.450 mi
Registration #23	2018-09-18	73.450 mi
Registration #24	2018-09-18	73.450 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1803 mm
Height	1397 mm
Length	4114 mm
Wheel base	2440 mm
Kerb weight	1110 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4EA4508700