





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 16V
Colour	Blue
Year of manufacture	2011
Top speed	100 mph
0 - 60 mph	15.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	126 Nm at 3.300 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	171 g/km
CO2 label	Н



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-10-25

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-18
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	10
Total items failed	6

MOT #14	2024-04-10 10:51
MOT test number	605877150528
Result	✓ Passed
Next expiry date	2025-04-18
Advice Nearside Front Tyre slightly damaged/cracking or perishing damage on outer side wall (5.2.3 (d) (ii))	
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #13	2023-03-28 12:25
MOT test number	130334941945
Result	✓ Passed

MOT #12	2022-04-19 15:35
MOT test number	719486382055
Result	✓ Passed

MOT #11		2021-10-22 15:05
MOT test	number	413054073506
Result		✓ Passed
Advice	Offside Front Nail in tyre	
Advice	High level stop light not working corrosion off side rear sill	
Advice	Items removed from driver's view prior to test	

CarCheck.co.uk page 3/12



MOT #10 2021-10-22 15:05

MOT test number 442372350268

Result X Failed

Pass with rectification

Offside Headlamp not working on main beam repair multi plug connection (4.1.1 (a) (ii))

Advice Items removed from driver's view prior to test

Advice High level stop light not working corrosion off side rear sill

Pass with rectification Offside Headlamp not working on dipped beam repair headlamp multi plug connection (4.1.1 (a) (ii))

Advice Offside Front Nail in tyre

Pass with rectification Offside Position lamp not working repair multi plug connection (4.2.1 (a) (ii))

MOT #9 2020-10-16 10:59

MOT test number 229467332299

Result
✓ Passed

Advice Rear exhaust silencer becoming corroded

MOT #8 2020-10-16 10:04

MOT test number 109000210492

Result ★ Failed

Fail Nearside Headlamp aim not tested (4.1.2 (b))

Advice Rear exhaust silencer becoming corroded

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7 2019-04-23 07:55

MOT test number 695124719734

Result

Passed

CarCheck.co.uk page 4/12



Result

AO11NZA report date: 2024-03-28

✓ Passed

MOT #6	2018-04-20 08:31
MOT test number	284719365328

MOT #5	2017-04-27 09:20
MOT test number	171200175275

MOT #4 2016-04-12 15:58

MOT test number 750992829661

Result ✓ Passed

MOT #3

MOT test number

Result

Pass with rectification

Nearside Registration plate lamp not working (1.1.C.1d)

MOT #2	2015-04-07 17:06
MOT test number	975387495027
Result	✓ Passed

MOT #1	2014-04-10 15:07
MOT test number	147460104142
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



AO11NZA

report date: 2024-03-28


Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	K UK
Plate since	
	More info >
	More into /

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-22
Last registration	2024-04-10
Complete history	See info



Registration #1	2011-04-22	18 mi
Registration #2	2014-04-10	21.629 mi
Registration #3	2015-04-07	27.943 mi
Registration #4	2016-04-12	32.995 mi
Registration #5	2016-04-12	32.995 mi
Registration #6	2017-04-27	38.505 mi
Registration #7	2018-04-20	43.512 mi
Registration #8	2019-04-23	49.557 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 ms
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1373 kg

Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

CarCheck.co.uk page 12/12

Number of axles	2

BCA 569429

Engine number