



TOYOTA

KF03DFX


report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Silver
Year of manufacture	2003
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	44.1 mpg
CO2 emission	190 g/km
CO2 label	J





MOT history

MOT expiry date	2021-06-22
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	33
Total items failed	2

MOT #18	2020-06-23 15:18
MOT test number	705419061670
Result	✓ Passed
Next expiry date	2021-06-22
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing wearing low on tread (5.2.3 (d) (ii))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing wearing low on tread (5.2.3 (d) (ii))

**MOT #17**

2020-06-23 09:32

MOT test number

621840292473

Result

✗ Failed

- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing wearing low on tread (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing wearing low on tread (5.2.3 (d) (ii))
- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- MAJOR** Offside Headlamp insecure (4.1.1 (c))

MOT #16

2019-04-01 12:43

MOT test number

520435191439

Result

✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #15

2018-04-10 13:28

MOT test number

102671010961

Result

✓ Passed

- Advice** Offside Rear tyre starting to crack in tread.
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #14

2017-03-27 13:51

MOT test number

777876704719

Result

✓ Passed

- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #13** 2017-03-27 12:23**MOT test number** 598261469604**Result** ✗ Failed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #12** 2016-03-24 10:21**MOT test number** 677408134220**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #11** 2015-03-06 13:27**MOT test number** 359175965033**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #10** 2015-03-06 13:18**MOT test number** 148675465417**Result** ✗ Failed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Brake hydraulic reservoir cap missing (3.6.G.1a)**MOT #9** 2014-03-18 15:51**MOT test number** 597677274024**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #8** 2013-03-12 13:29**MOT test number** 689471773053**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2012-03-15 13:42**MOT test number** 248565972095**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2011-03-03 10:47**MOT test number** 365292361036**Result** ✓ Passed**MOT #5** 2010-03-16 11:34**MOT test number** 284085770027**Result** ✓ Passed

**MOT #4** 2009-03-31 13:06**MOT test number** 490180299093**Result** ✓ Passed

- Notice** O/s/r tyre mis-shaped and perishing
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Both front tyres beginning to perish
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** N/s/r tyre beginning to mis-shape and perishing
- Notice** Rear number plate fading

MOT #3 2008-02-12 15:19**MOT test number** 350963948003**Result** ✓ Passed**MOT #2** 2007-02-22 11:00**MOT test number** 164373557014**Result** ✓ Passed**MOT #1** 2006-02-23 11:43**MOT test number** 272694656058**Result** ✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
21 December 2020

×

MOT

Expired:
22 June 2021

Tax status

Expired at 21 December 2020

Days left

1226 days too late

MOT expiry date

22 June 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	KF03DFX
Plate since	2019-03-29
Current registration	KF03DFX
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2003-03-01
Last registration	2020-06-23
Complete history	See info



Registration #1	2003-03-01	15 mi
Registration #2	2006-02-23	20.469 mi
Registration #3	2007-02-22	26.471 mi
Registration #4	2008-02-12	31.207 mi
Registration #5	2009-03-31	37.402 mi
Registration #6	2010-03-16	41.035 mi
Registration #7	2011-03-03	44.239 mi
Registration #8	2012-03-15	46.287 mi
Registration #9	2013-03-12	47.569 mi
Registration #10	2014-03-18	48.463 mi
Registration #11	2015-03-20	49.357 mi
Registration #12	2016-03-20	50.251 mi
Registration #13	2017-03-20	51.145 mi
Registration #14	2018-03-20	52.039 mi
Registration #15	2019-03-20	52.933 mi
Registration #16	2020-03-20	53.827 mi
Registration #17	2021-03-20	54.721 mi
Registration #18	2022-03-20	55.615 mi
Registration #19	2023-03-20	56.509 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1250 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

Engine number

3ZZU341231