





report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Orange
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Emter.	1
Entry	т.

ciitiy 1	
Date	2021-08-31
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-01-03
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	25
Total items failed	7

MOT #19		2023-12-21 11:39
MOT test	number	971461300560
Result		✓ Passed
Next expi	ry date	2025-01-03
Advice	Nearside Non obligatory mirror damaged	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #18			2023-12-21 11:39
MOT test r	number		803053750775
Result			× Failed
Pass wit	h rectification	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	
Advice	Nearside Rear Ty	re slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Non ob	ligatory mirror damaged	
Pass wit	h rectification	Offside Rear Position lamp adversely affected by the op	eration of another lamp
(4.2.3 (c))			
Advice	Offside Rear Tyre	e slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #17	2022-12-23 14:05
MOT test number	895986865402
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #16

MOT test number

Result

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15 2021-12-28 13:12 **MOT** test number 114906031777 ✓ Passed Result **MOT #14** 2021-01-04 10:18 **MOT** test number 537233172315 Result ✓ Passed **Advice** Offside Front Valve stem slightly misaligned (5.2.3 (j)) **Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice **Advice** Auxiliary belt perished

MOT #13 2021-01-04 10:18 **MOT** test number 898724758666 Result × Failed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Auxiliary belt perished Advice Offside Front Valve stem slightly misaligned (5.2.3 (j)) **Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12

MOT test number

412363560170

Result

Advice Nearside Rear Water in light cluster

Advice Items removed from driver's view prior to test

Advice Offside Rear Water in light cluster

Offside Rear Water in light cluster

Offside Rear Water in light cluster

Oil level low on dipstick

MOT #11 2019-12-28 10:24 935140589079 **MOT** test number × Failed Result **Advice** Nearside Rear Water in light cluster Pass with rectification Offside Headlamp aim too low (4.1.2 (a)) Items removed from driver's view prior to test Advice Advice Offside Rear Water in light cluster Advice Oil level low on dipstick

MOT #10

MOT test number

Result

Advice Offside Rear Nail in tyre

Advice Nearside Front Nail in tyre

Advice Coolant leak

Coolant leak

 MOT #9
 2017-12-30 09:58

 MOT test number
 362472284969

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



MOT #8

MOT #4

Result

MOT test number

EN57BXB

report date: 2024-03-29

2017-12-30 09:58

2013-12-12 14:56

319236243315

✓ Passed

MOT test number		662013642891
Result		≍ Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)	
Pass with rectification	Nearside Stop lamp not working (1.2.1b)	
MOT #7		2016-12-22 08:49
MOT test number		499316583819
Result		✓ Passed
MOT #6		2016-01-04 15:00
MOT test number		101569992271
Result		✓ Passed
MOT #5		2014-12-04 14:54
MOT test number		546508634315
Result		✓ Passed

MOT test number	515080542378
MOT #3	2012-12-05 14:53

Result \rightarrow Passed

MOT #2	2011-11-23 14:59
MOT test number	939927021376
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1 2010-12-14 15:15

MOT test number 250978140356

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
HEREEN CO.	

THE STREET STREE	
HARMAN AND AND AND AND AND AND AND AND AND A	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-01-18
Last registration	2023-12-21
Complete history	See info



Registration #1	2008-01-18	26 mi
Registration #2	2010-12-14	18.652 mi
Registration #3	2011-11-23	20.490 mi
Registration #4	2012-12-05	21.873 mi
Registration #5	2013-12-12	23.450 mi
Registration #6	2014-12-04	24.569 mi
Registration #7	2016-01-04	26.073 mi
Registration #8	2016-12-22	29.967 mi
Registration #9	2017-12-30	34.114 mi
Registration #10	2017-12-30	34.114 mi
Registration #11	2018-12-12	42.096 mi
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 es
Registration #18		11.777 es
Registration #19		11.117 es
Registration #20		11.177 es
Registration #21		77.777 mg

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

Engine number 8A48618