





report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER LH35 DCI H/R P/V
Colour	White
Year of manufacture	2012
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	38.6 mpg
Consumption combined	34.8 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-08-22
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	10
Total items failed	20

MOT #14	2023-08-23 10:34
MOT test number	700876380700
Result	✓ Passed
Next expiry date	2024-08-22
Advice Front Shock absorbers has light misting of oil N/S & O/S (5.3.2 (b))	

MOT #13	2023-08-23 10:34	
MOT test number	645202040881	
Result	X Failed	
Advice Front Shock absorbers has light misting of oil N/S & O/S (5.3.2 (b))		
Pass with rectification	Nearside Front Drive shaft joint constant velocity boot split or insecure, no	
longer prevents the ingress of dirt (6.1.7 (g) (ii))		

MOT #12		2022-04-29 10:46
MOT test	number	415067793871
Result		✓ Passed
Advice	Front Shock absorbers has light misting of oil N/S & O/S (5.3.2 (b))	
Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (D- Bush) (5.3.4 (a) (i))		

CarCheck.co.uk page 2/12



MOT #11 2022-04-29 10:46

MOT test number 341553514948

Result X Failed

Advice Front Shock absorbers has light misting of oil N/S & O/S (5.3.2 (b))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (D- Bush) (5.3.4 (a) (i))

MOT #10 2021-01-13 15:17

MOT test number 878512805372

Result ✓ Passed

MOT #9 2019-06-25 16:07

MOT test number 544744666996

Result ✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 3/12



Result

LV12YRA report date: 2024-03-29

× Failed

MOT #8 2019-06-25 07:51

MOT test number 336666732239

Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Central Outline marker lamp not working Nearside (4.2.1 (a) (ii))

Fail Central Stop lamp(s) showing white light to the rear (4.3.3 (a) (ii))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Rear Outline marker lamp not working (4.2.1 (a) (ii))

Fail Central Stop lamp(s) lens defective such that the emitted light is adversely affected (4.3.1 (b) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7 2018-06-02 11:08

MOT test number 531007191713

Result \(\sqrt{Passed} \)

MOT #6 2018-06-02 11:08

MOT test number 598234209855

Result X Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Pass with rectification Offside Rear All direction indicators incorrect colour (4.4.3 (a))

Pass with rectification Nearside Rear All direction indicators incorrect colour (4.4.3 (a))

Pass with rectification Offside Front All direction indicators incorrect colour (4.4.3 (a))

CarCheck.co.uk page 4/12



MOT #5

LV12YRA
report date: 2024-03-29

2017-06-19 14:21

MOT test number 547320705818

MOT #4 2017-06-15 13:20

MOT test number 658023998598

Result X Failed

Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #3 2016-06-30 14:20

MOT test number 244706558366

Result ✓ Passed

MOT #2 2015-06-24 14:50

MOT test number 267145475191

Result
✓ Passed

MOT #1 2015-06-20 09:44

MOT test number 965261875137

Result ★ Failed

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

Fail Offside Headlamp aim too high (1.8)

CarCheck.co.uk page 5/12





Tax & MOT check

Tax expired: 1 April 2024





Expires: 22 August 2024

Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manage of the same	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	EX UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-21
Last registration	2023-08-23
Complete history	See info



Registration #1	2012-06-21	26 mi
Registration #2	2015-06-20	97.428 mi
Registration #3	2015-06-24	97.641 mi
Registration #4	2016-06-30	118.212 mi
Registration #5	2017-06-15	133.684 mi
Registration #6	2017-06-19	133.686 mi
Registration #7	2018-06-02	150.928 mi
Registration #8	2018-06-02	150.928 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Additional information

Fuel tank capacity	105 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C043635

CarCheck.co.uk page 12/12