



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D4 BUSINESS EDITION
Colour	Black
Year of manufacture	2014
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-09-07
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-05
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #9	2023-11-28 10:50
MOT test number	768813132164
Result	✓ Passed
Next expiry date	2024-12-05

MOT #8	2022-12-06 10:57
MOT test number	107209161557
Result	✓ Passed

MOT #7	2021-12-03 09:44
MOT test number	747382396045
Result	✓ Passed

MOT #6	2021-08-12 16:01
MOT test number	639814452947
Result	✓ Passed

**MOT #5** 2021-06-25 08:38**MOT test number** 841781765449**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Engine cover and undertray fitted obscuring some components**Advice** Items removed from driver's view prior to test**MOT #4** 2020-07-01 16:20**MOT test number** 944426175323**Result** ✓ Passed**MOT #3** 2019-03-20 12:47**MOT test number** 762613590320**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 215/50/17 2mm (5.2.3 (e))**MOT #2** 2018-03-06 13:10**MOT test number** 290852677707**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit worn to 3.0 mm 215/50 x 17 95 w (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit worn to 3.0 mm (4.1.E.1)



MOT #1	2017-03-02 11:44
MOT test number	973079137716
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
5 December 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	5 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-31
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2014-03-31	21 mi
Registration #2	2017-03-02	71.407 mi
Registration #3	2018-03-06	88.601 mi
Registration #4	2019-03-20	108.187 mi
Registration #5	2020-07-01	131.228 mi
Registration #6	2021-06-25	147.674 mi
Registration #7	2022-06-29	161.277 mi
Registration #8	2022-06-29	161.277 mi
Registration #9	2022-06-29	161.277 mi
Registration #10	2022-06-29	161.277 mi
Registration #11	2023-11-28	161.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1606 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1136390