



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XT
Colour	Silver
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	343 Nm at 1.850 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	204 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-02-28
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	11
Total items failed	12

MOT #19	2023-02-28 16:22
MOT test number	523094387373
Result	✓ Passed
Next expiry date	2024-02-28

MOT #18	2023-02-27 16:26
MOT test number	545377220348
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #17	2022-03-01 19:18
MOT test number	655101041764
Result	✓ Passed

**MOT #16**

2022-02-23 17:26

MOT test number

708101731930

Result**✗ Failed**

Fail Nearside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced Sill (7.1.1 (a) (i))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced Sill (7.1.1 (a) (i))

Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #15

2021-04-22 13:13

MOT test number

422393572407

Result**✓ Passed****MOT #14**

2021-04-19 12:47

MOT test number

928249308539

Result**✗ Failed**

Advice N/s centre inner sill corroded and holed, unable to determine if within seat belt prescribed area.

Advice Brake pipe corroded, covered in grease or other material n/s and o/s front (1.1.11 (c))

Advice N/s and o/s rear inner sills corroded and holed, non structural component, unable to determine if within seat belt prescribed area.

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13

2020-08-03 08:58

MOT test number

770528000663

Result**✓ Passed**

**MOT #12** 2020-08-03 08:00**MOT test number** 489625962153**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**MOT #11** 2019-08-02 09:06**MOT test number** 880143235897**Result** ✓ Passed**MOT #10** 2018-09-03 10:54**MOT test number** 738465087837**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #9** 2017-09-14 10:09**MOT test number** 425347990760**Result** ✓ Passed**MOT #8** 2016-07-13 09:51**MOT test number** 288506094028**Result** ✓ Passed




MOT #7	2015-07-31 10:52
MOT test number	356452515495
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
MOT #6	2014-06-26 10:59
MOT test number	877867974139
Result	✓ Passed
MOT #5	2013-06-07 11:47
MOT test number	286498453469
Result	✓ Passed
MOT #4	2012-06-29 15:52
MOT test number	557081782188
Result	✓ Passed
MOT #3	2011-06-24 16:45
MOT test number	898845971119
Result	✓ Passed
MOT #2	2010-06-28 16:52
MOT test number	803549870196
Result	✓ Passed
MOT #1	2009-05-16 10:10
MOT test number	784706139159
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	L14LJX
Plate since	2024-03-28
Current registration	L14LJX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-06-16
Last registration	2023-02-28
Complete history	See info



Registration #1	2006-06-16	12 mi
Registration #2	2009-05-16	13.641 mi
Registration #3	2010-06-28	21.523 mi
Registration #4	2011-06-24	32.151 mi
Registration #5	2012-06-29	41.381 mi
Registration #6	2013-06-07	48.439 mi
Registration #7	2014-06-26	56.455 mi
Registration #8	2015-07-31	65.329 mi
Registration #9	2016-07-13	69.484 mi
Registration #10	2017-09-14	74.429 mi
Registration #11	2018-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2021-05-20	75.377 mi
Registration #15	2022-05-20	75.377 mi
Registration #16	2023-05-20	75.377 mi
Registration #17	2024-05-20	75.377 mi
Registration #18	2025-05-20	75.377 mi
Registration #19	2026-05-20	75.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1804 mm
Length	4567 mm
Wheel base	2710 mm
Kerb weight	2056 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB5878441