





## General information

Make	VOLVO
Model	V50 D DRIVE S
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg





Internet history	
Entry 1	
Date	2021-12-30
Pictures	0
Listing price	View report

source: autotrader.co.uk



<b>AY59YUO</b>
report date: 2024-03-29

MOT history	
MOT #13	2023-11-15 09:35
MOT test number	927509508683
Result	✓ Passed
Next expiry date	2024-11-22
MOT #12	2022-11-23 13:50
MOT test number	497765100322
Result	✓ Passed
MOT #11	2022-11-23 11:48
MOT test number	124639576689
Result	× Failed
<b>MAJOR</b> Nearside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))	
MOT #10	2021-09-13 13:32
MOT #10 MOT test number	389936629867
Result	✓ Passed
<b>VESUI</b>	✓ Fasseu
MOT #9	2020-09-15 14:10
MOT test number	932671539487

Result

Advice

Offside Front STRUT SPRING SEAT IS DAMP

MOT #8	2019-09-12 14:19
MOT test number	884342173334
Result	✓ Passed
Advice SILL COVERS FITTED	

✓ Passed





MOT #7	2018-09-07 14:09
MOT test number	705124496514
Result	✓ Passed
Advice SILL COVERS FITTED	
MOT #6	2017-09-05 14:08
MOT test number	416296650607
Result	✓ Passed
Advice Engine under tray fitted	
Advice Items removed from driver's view prior to test	
MOT #5	2016-09-09 10:29
MOT test number	699668543204
Result	✓ Passed
MOT #4	2015-09-10 14:07
MOT test number	299808236450
Result	✓ Passed
MOT #3	2014-09-05 14:43
MOT test number	895848644248
Result	✓ Passed
MOT #2	2013-09-05 15:56
MOT test number	588898343240
Result	✓ Passed
Notice Front brake pads worn low	





MOT #1	2012-09-05 14:49
MOT test number	599109442274
Result	✓ Passed
<b>Notice</b> Offside front tyre tread cut but not to chords	





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	
***********	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Current registration Pate since	





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-18
Last registration	2023-11-15
Complete history	See info



Registration #1	2009-09-18	23 mi
Registration #2	2012-09-05	33.146 mi
Registration #3	2013-09-05	43.293 mi
Registration #4	2014-09-05	54.075 mi
Registration #5	2015-09-10	64.703 mi
Registration #6	2016-09-09	74.556 mi
Registration #7	2017-09-05	83.418 mi
Registration #8	2018-09-07	92.300 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi





## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg
Additional information	
Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/11