





report date: 2024-03-28

## General information

Make	FORD
Model	FIESTA
Colour	Black
Year of manufacture	2012
Gearbox	-

## Engine & fuel consumption

Engine capacity	1.399 сс
Fuel type	Diesel
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/14



report date: 2024-03-28


## Internet history


## Entry 1

Date 2021-10-23

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

## MOT history

MOT expiry date	2024-11-12
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	29
Total items failed	9

MOT #16		2023-11-13 08:51
MOT test number	r	698320527815
Result		<b>✓</b> Passed
Next expiry date		2024-11-12
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))		
<b>Minor</b> Offside	Front Outer Drive shaft joint constant velocity boot severe	ely deteriorated (6.1.7 (g) (i))

MOT #15	2023-11-10 12:01	
MOT test number	127377536524	
Result	<b>X</b> Failed	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3	.4 (a) (i))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot sev	verely deteriorated (6.1.7 (g) (i))	
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))		
Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))		
Minor Offside Front Outer Drive shaft joint constant velocity boot seven	rely deteriorated (6.1.7 (g) (i))	
Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))		

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #14

MOT test number

691148281958

Result

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Rear All direction indicators slightly discoloured (4.4.3 (a))

Advice Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #13** 2022-10-19 08:57 **MOT** test number 470550927070 Result × Failed Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Minor Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Offside Rear Road wheel slightly distorted (5.2.2 (c) (i)) Advice **Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a))

MOT #12	2021-10-26 15:32
MOT test number	340616196529
Result	<b>✓</b> Passed

MOT #11	2020-12-30 16:04
MOT test number	671389500777
Result	✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #10 2020-12-30 12:27

MOT test number 672841346175

Result

× Failed

Fail

Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn BOTH (5.1.2 (b) (i))

MOT #9 2019-12-23 15:21

MOT test number 698200064777

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8 2019-12-23 12:31

**MOT test number** 336736596154

Result X Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #7 2019-01-02 14:58

**MOT test number** 491009775208

MOT #6 2018-03-22 14:39

**MOT test number** 189816881411

**Result** ✓ Passed

**Advice** Offside Rear coil spring corroded (2.4.C.1b)

**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

CarCheck.co.uk page 5/14



report date: 2024-03-28

**MOT #5** 2018-03-19 18:42 256541008555 **MOT** test number Result × Failed **Advice** Engine management light on Fail Nearside Front Front wheel bearing rough when rotated (2.5.A.2) **Advice** Exhaust back box outer skin corroded Advice Offside Rear coil spring corroded (2.4.C.1b) Both front discs corroded and scored Advice **Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT test number

Result

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear coil spring corroded (2.4.C.1b)

MOT #3

MOT test number

704568339162

Result

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)

Advice Offside Rear coil spring corroded (2.4.C.1b)

 MOT #2
 2015-05-12 16:15

 MOT test number
 859372935124

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2015-05-11 12:50

**MOT test number** 107291835190

**Result** X Failed

Fail Offside Front Mechanical brake component has restricted free movement (3.5.1k)

CarCheck.co.uk page 7/14



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

# Owner history

*	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
manus .	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	SK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-06-26
Last registration	2023-11-13
Complete history	See info



Registration #1	2012-06-26	22 mi
Registration #2	2015-05-11	19.083 mi
Registration #3	2015-05-12	19.083 mi
Registration #4	2016-04-19	29.188 mi
Registration #5	2017-03-28	37.263 mi
Registration #6	2018-03-19	48.293 mi
Registration #7	2018-03-22	48.293 mi
Registration #8	2019-01-02	50.945 mi
Registration #9	2019-12-23	61.522 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Additional information

Number of seats	5
Engine number	CA09045

CarCheck.co.uk page 14/14