



report date: 2024-03-29

General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	Silver
Year of manufacture	2013
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 3


Date	2023-01-30
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2023-01-15
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2023-01-01
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-28
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	15

MOT #11	2023-08-30 13:02
MOT test number	486680162131
Result	✓ Passed
Next expiry date	2024-09-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Anti-roll bar ball joint dust cover severely deteriorated both front (5.3.4 (b) (i))

MOT #10	2022-09-24 09:19
MOT test number	722771038902
Result	✓ Passed

MOT #9	2021-09-27 14:08
MOT test number	181171222272
Result	✓ Passed

**MOT #8**

2021-09-23 14:28

MOT test number

583146160514

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Fail** Headlamp aim not tested (4.1.2 (b))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))**Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #7** 2020-09-25 10:53**MOT test number** 257565691011**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2019-09-27 10:11**MOT test number** 781859686958**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2018-09-27 15:23**MOT test number** 255223641077**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2017-09-29 08:34**MOT test number** 583663082432**Result** ✓ Passed**MOT #3** 2017-04-21 10:27**MOT test number** 836403513450**Result** ✓ Passed**Advice** N.s.f tyre poor condition, side wall damaged, bald on edge and 2.2mm



MOT #2	2017-04-21 10:27
MOT test number	516718519966
Result	✗ Failed
Advice	N.s.f tyre poor condition, side wall damaged, bald on edge and 2.2mm
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively Both (8.2.2)
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
MOT #1	2016-04-02 09:39
MOT test number	739577847041
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
28 September 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-04-30
Last registration	2023-08-30
Complete history	See info



Registration #1	2013-04-30	7 mi
Registration #2	2016-04-02	32.915 mi
Registration #3	2017-04-21	41.604 mi
Registration #4	2017-04-21	41.604 mi
Registration #5	2017-09-29	46.478 mi
Registration #6	2018-09-27	67.099 mi
Registration #7	2019-09-27	87.995 mi
Registration #8	2020-09-25	103.945 mi
Registration #9	2020-09-25	103.945 mi
Registration #10	2020-09-25	103.945 mi
Registration #11	2020-09-25	103.945 mi
Registration #12	2020-09-25	103.945 mi
Registration #13	2020-09-25	103.945 mi
Registration #14	2020-09-25	103.945 mi
Registration #15	2020-09-25	103.945 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBET0001963