





General information

Make	VAUXHALL
Model	ASTRA
Colour	Silver
Year of manufacture	2018
Top speed	129 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	52.3 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history


Entry 3

Date Pictures 2021-09-06

27

Listing price

View report



source: yesauto.com

Entry 2	
Date	2021-09-05
Pictures	28
Listing price	View report










source: cargurus.co.uk

Entry 1Date2021-09-03Pictures28Listing priceView report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-01
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	21
Total items failed	3

MOT #4	2023-10-02 15:42
MOT test number	697232145520
Result	✓ Passed
Next expiry date	2024-10-01
Advice Items removed from driver's view prior to test	
Advice Offside Rear Nail in tyre nail in the tread leaking tyre is also out of shape	
Advice Offside Front Play in steering rack inner joint(s)	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front Play in steering rack inner joint(s) Advice Nearside Deep Time has a sub but not deep anough to use show a sublement of the second statement of the secon	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords	
Minor Windscreen wiper blade defective front wipers poor aero deck blades fitted (3	5.4 (D) (I))



FG68WCP report date: 2024-03-29

MOT #3 2023-10-02 14:40
MOT test number 218111585651
Result X Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm 225/40/18 (5.2.3 (e))
Advice Coolant level was low
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice Items removed from driver's view prior to test
Fail Offside Headlamp aim too low (4.1.2 (a))
Advice Offside Rear Nail in tyre nail in the tread leaking tyre is also out of shape
Minor Windscreen wiper blade defective front wipers poor aero deck blades fitted (3.4 (b) (i))
Advice Offside Front Tyre worn close to legal limit/worn on edge STRONG ADVISE tyre is on legal limit and also has a nail in the tread (5.2.3 (e))
Advice Offside Front Play in steering rack inner joint(s)
Fail Nearside Headlamp aim too high (4.1.2 (a))
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice Nearside Front Play in steering rack inner joint(s)

MOT #2		2022-08-11 13:54
MOT test	number	909311165263
Result		✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Items removed from driver's view prior to test	
Advice	Offside Front Play in steering rack inner joint(s)	





MOT #1	2021-08-24 16:31
MOT test number	722699063107
Result	✓ Passed



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 June 2024	Expires: 1 October 2024
Tax status	Valid until 1 June
Days left	34
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	₩ UK
Ender class	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-29
Last registration	2023-10-02
Complete history	See info



Registration #1	2018-09-29	25 mi
Registration #2	2021-08-24	47.319 mi
Registration #3		11.777 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.317 esi

More info \rightarrow





Safety ratings

NCAP rating	****	
Adult	86%	
Children	84%	
Pedestrian	83%	Portical 2
Safety systems	75%	
Overall rating	83%	
Video	<u>see crash video</u>	
		Copyright © 2015 Euro

Dimensions & weight	
Width	1809 mm
Height	1485 mm
Length	4370 mm
Wheel base	2662 mm
Kerb weight	1318 kg
Max. allowed weight	1920 kg
Additional information	
Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	
	5
Number of seats	5 5