





M /

General information

Make	BMW
Model	530 535D M SPORT TOURING
Colour	Blue
Year of manufacture	2010
Gearbox	8 speed automatic

Engine & fuel consumption

Power	299 BHP	0 < 101 A
Engine capacity	2.993 cc	101 - 120 ^B _C
Cylinders	6	121 - 140 E
Fuel type	Diesel	141 - 165 F LABE
CO2 emission	165 g/km	166 - 185 H
CO2 label	G	186 - 225 <mark>У</mark> К
		225+ L



Internet history

Entry 1

Date


Pictures

Listing price

2021-11-20

12

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-31
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	18
Total items failed	6

MOT #16		2024-01-30 14:40
MOT test	number	940322019204
Result		✓ Passed
Next expi	ry date	2025-01-31
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #15	2023-02-01 17:16
MOT test number	652931926522
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #14	2023-01-31 14:06
MOT test number	400935021909
Result	🗙 Failed
MinorWindscreen damaged but not adversely affecting driver's view (3.2 (a) (i))FailFront Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail Nearside Front Hydraulic brake calliper inadequately mounted (1.1.16 (c) (i))	



MOT #13

Result

MOT test number

ĸ	report date: 2024-03-28
	2022-01-29 12:56
	638061269469
	✓ Passed

HN60ANY

2022-01-29 11:03
227910435627
🗙 Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11	2021-07-06 11:08
MOT test number	354339918298
Result	✓ Passed
Advice Nearside Headlamp has a product on the light source but not seriously reducing light output water	

in lamp (4.1.4 (b))

MOT #10	2020-07-08 12:48
MOT test number	308047673024
Result	✓ Passed

MOT #9	2020-07-07 12:04	
MOT test number	245111015677	
Result	🗙 Failed	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		

MOT #8	2019-08-14 12:52
MOT test number	106301603554
Result	✓ Passed



HN60ANX report date: 2024-03-28

MOT #7	2019-08-13 13:31
MOT test number	651562933837
Result	🗙 Failed
Fail Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MOT #6	2018-03-06 14:34
MOT test number	534656508943
Result	🗸 Passed
Advice Offside Rear tyre is slightly worn on inner edge	
MOT #5	2017-03-10 14:04
MOT test number	808162752205
Result	✓ Passed
MOT #4	2015-10-17 08:33
MOT test number	745105690768
Result	Passed
MOT #3	2014-09-18 10:05
MOT test number	665001564281
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Engine covers fitted obscuring some components in the engine bay	



MOT #2		2013-09-20 16:40
MOT test	number	515103663268
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	
MOT #1		2013-09-20 13:06
MOT test	number	925113963234
Result		🗙 Failed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Under-trays fitted obscuring some underside components	

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Notice Engine covers fitted obscuring some components in the engine bay

HN60ANX

report date: 2024-03-28





Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 31 January 2025
Tax status	Valid until 1 February
Days left	278
MOT expiry date	31 January 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lashe
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	 *
Category	 amer
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

1000000	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



HN60ANX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-10-15
Last registration	2024-01-30
Complete history	See info



Registration #1	2010-10-15	11 mi
Registration #2	2013-09-20	45.277 mi
Registration #3	2013-09-20	45.278 mi
Registration #4	2014-09-18	55.832 mi
Registration #5	2015-10-17	59.989 mi
Registration #6	2017-03-10	62.540 mi
Registration #7	2018-03-06	64.507 mi
Registration #8	2019-08-13	67.985 mi
Registration #9	2019-08-14	67.985 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 est





Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
0567	
0569	

Safety ratings

NCAP rating	****
Adult	95%
Children	83%
Pedestrian	78%
Safety systems	100%
Overall rating	90%
Video	see crash video



Dimensions & weight	
Width	2102 mm
Height	1462 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1840 kg
Max. allowed weight	2490 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number Carcheck.co.uk	35287624 page 13/13