




General information

Make	FORD
Model	FOCUS ST-3
Colour	Orange
Year of manufacture	2010
Top speed	150 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	223 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



## MOT history

MOT expiry date	2025-02-23
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	9
Total items failed	10

MOT #18	2024-02-22 11:00
MOT test number	543209577246
Result	✓ Passed
Next expiry date	2025-02-23

MOT #17	2023-02-14 16:37
MOT test number	932900362439
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2023-02-09 15:12
MOT test number	588052298816
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15** 2022-02-24 15:08**MOT test number** 673181595698**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #14** 2021-02-23 16:36**MOT test number** 472118423042**Result** ✓ Passed**MOT #13** 2021-02-22 12:55**MOT test number** 954598475929**Result** ✗ Failed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12** 2020-03-18 13:42**MOT test number** 421869445256**Result** ✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush both sides (5.3.4 (a) (i))

**MOT #11** 2020-03-18 13:42**MOT test number** 129242837132**Result** ✗ Failed

**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush both sides (5.3.4 (a) (i))

**MOT #10** 2019-03-21 08:46**MOT test number** 789329903396**Result** ✓ Passed**MOT #9** 2018-03-27 14:36**MOT test number** 136317511310**Result** ✓ Passed**MOT #8** 2017-03-09 16:32**MOT test number** 346331812801**Result** ✓ Passed**MOT #7** 2017-03-09 10:58**MOT test number** 994196813204**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2016-03-15 09:17**MOT test number** 862099773067**Result** ✓ Passed**MOT #5** 2015-03-31 16:36**MOT test number** 265720395047**Result** ✓ Passed



<b>MOT #4</b>	2015-03-26 16:31
---------------	------------------

<b>MOT test number</b>	857625485082
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Offside Side repeater not working (1.4.A.2c)
-------------	--

<b>MOT #3</b>	2014-03-26 13:59
---------------	------------------

<b>MOT test number</b>	935775384085
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-03-26 08:46
---------------	------------------

<b>MOT test number</b>	178475584003
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---

<b>MOT #1</b>	2013-03-28 11:37
---------------	------------------

<b>MOT test number</b>	348777583000
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
23 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	23 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-04-16
Last registration	2024-02-22
Complete history	<a href="#">See info</a>



Registration #1	2010-04-16	26 mi
Registration #2	2013-03-28	22.398 mi
Registration #3	2014-03-26	29.071 mi
Registration #4	2014-03-26	29.703 mi
Registration #5	2015-03-26	36.205 mi
Registration #6	2015-03-31	36.246 mi
Registration #7	2016-03-15	44.697 mi
Registration #8	2017-03-09	52.304 mi
Registration #9	2017-03-09	52.306 mi
Registration #10	2018-03-27	64.276 mi
Registration #11	2019-03-20	75.277 mi
Registration #12	2019-03-20	75.277 mi
Registration #13	2019-03-20	75.277 mi
Registration #14	2019-03-20	75.277 mi
Registration #15	2019-03-20	75.277 mi
Registration #16	2019-03-20	75.277 mi
Registration #17	2019-03-20	75.277 mi
Registration #18	2019-03-20	75.277 mi
Registration #19	2019-03-20	75.277 mi
Registration #20	2019-03-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1839 mm
Height	1497 mm
Length	4357 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	AU03984