



report date: 2024-03-28

General information

| | |
|---------------------|--------------------------------|
| Make | LAND ROVER |
| Model | RANGE ROVER SDV6 AUTOBIOGRAPHY |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 130 mph |
| 0 - 100 km/h | 7.9 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 202 kW / 275 HP / 271 BHP |
| Max. torque | 625 Nm at 1.500 rpm |
| Engine capacity | 2.993 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 26.7 mpg |
| Consumption extra urban | 34.1 mpg |
| Consumption combined | 31.4 mpg |
| CO2 emission | 199 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-08-06 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-14 |
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 3 |
| Total items failed | 0 |

| | |
|------------------|---------------------------------------------------------------------------------------------------------------------------------------|
| MOT #3 | 2023-08-15 15:12 |
| MOT test number | 538599585991 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-14 |
| Advice | Front Suspension arm pin or bush worn but not resulting in excessive movement Both front support arm bushes perished. (5.3.4 (a) (i)) |

| | |
|-----------------|----------------------------|
| MOT #2 | 2022-07-22 13:17 |
| MOT test number | 866754353179 |
| Result | ✓ Passed |
| Advice | Nearside Rear Nail in tyre |

| | |
|-----------------|--------------------------------------------------------------------------|
| MOT #1 | 2021-07-30 11:23 |
| MOT test number | 713706853668 |
| Result | ✓ Passed |
| Advice | Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 14 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|-------------------------------------------------------------|--------------|
| Vehicle class | 49 |
| Band | K |
| First licence fee (12 months) | £ 1.565,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 2.220,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | SR18OLP |
| Plate since | 2019-03-28 |
| Current registration | SR18OLP |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 5 |
| First mileage registration | 2018-08-15 |
| Last registration | 2023-08-15 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-08-15 | 29 mi |
| Registration #2 | 2021-07-30 | 34.670 mi |
| Registration #3 | 2022-07-22 | 49.184 mi |
| Registration #4 | 2023-08-15 | 55.557 mi |
| Registration #5 | 2023-08-15 | 55.557 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 84% |
| Pedestrian | 63% |
| Safety systems | 86% |
| Overall rating | 84% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2220 mm |
| Height | 1869 mm |
| Length | 5000 mm |
| Wheel base | 2922 mm |
| Kerb weight | 2253 kg |
| Max. allowed weight | 3130 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 86 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 1283008306DT |