



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC PRIVILEGE G/SCENIC EU4
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	152 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-25
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #20</b>	2023-08-21 15:06
<b>MOT test number</b>	482557462867
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-08-26
<b>Advice</b>	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
<b>Advice</b>	Offside Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

<b>MOT #19</b>	2023-08-15 08:54
<b>MOT test number</b>	573168529637
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
<b>Fail</b>	Bonnet cannot be secured in the closed position (3.1 (b) (i))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
<b>Fail</b>	Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #18</b>	2022-08-12 13:38
<b>MOT test number</b>	329906688333
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #17</b>	2022-08-12 13:38
<b>MOT test number</b>	445509654486
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

<b>MOT #16</b>	2021-08-27 09:44
<b>MOT test number</b>	467534682870
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))

<b>MOT #15</b>	2021-08-26 09:50
<b>MOT test number</b>	139307170102
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))
<b>Fail</b>	Nearside Front Headlamp aim too low (4.1.2 (a))

<b>MOT #14</b>	2020-12-03 16:48
<b>MOT test number</b>	617800683182
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Outer Play in steering rack inner joint(s)
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Exhaust mounting defective center exhaust (6.1.2 (a))
<b>Minor</b>	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13** 2019-11-15 17:01**MOT test number** 350521077738**Result** ✓ Passed**MOT #12** 2018-11-12 11:34**MOT test number** 259918184849**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #11** 2017-11-24 13:02**MOT test number** 514640475606**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #10** 2017-11-23 10:03**MOT test number** 209949072059**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Fail** Outer Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Stop lamp not working (1.2.1b)

**MOT #9** 2016-11-30 15:28**MOT test number** 651146551192**Result** ✓ Passed**Advice** Rear wiper blade split badly**Advice** Play in steering rack inner joint(s) both sides**MOT #8** 2015-11-27 12:50**MOT test number** 139989429684**Result** ✓ Passed**Advice** Rear wiper blade split**Advice** Direction indicators slightly discoloured (1.4.A.2f)**MOT #7** 2014-11-27 13:02**MOT test number** 549651934398**Result** ✓ Passed**MOT #6** 2014-11-27 13:02**MOT test number** 738351934368**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2013-11-29 14:58**MOT test number** 886303033303**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Notice** Play in steering rack inner joint(s)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)



MOT #4	2012-11-16 14:48
MOT test number	795701122323
Result	✓ Passed
Advice	Nearside Track rod end ball joint has slight play (2.2.B.1f)
Notice	Play in steering rack inner joint(s)

MOT #3	2011-11-25 10:53
MOT test number	597709221383
Result	✓ Passed

MOT #2	2010-11-26 12:27
MOT test number	204740730366
Result	✓ Passed

MOT #1	2009-11-27 12:56
MOT test number	230601039334
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-11-30
Last registration	2023-08-21
Complete history	<a href="#">See info</a>



Registration #1	2006-11-30	16 mi
Registration #2	2009-11-27	8.793 mi
Registration #3	2010-11-26	12.159 mi
Registration #4	2011-11-25	15.929 mi
Registration #5	2012-11-16	19.764 mi
Registration #6	2013-11-29	23.551 mi
Registration #7	2014-11-27	26.912 mi
Registration #8	2015-11-27	30.278 mi
Registration #9	2016-11-30	33.419 mi
Registration #10	2017-11-23	45.111 mi
Registration #11	2017-11-24	45.140 mi
Registration #12	2018-05-29	51.377 mi
Registration #13	2018-05-29	51.377 mi
Registration #14	2018-05-29	51.377 mi
Registration #15	2018-05-29	51.377 mi
Registration #16	2018-05-29	51.377 mi
Registration #17	2018-05-29	51.377 mi
Registration #18	2018-05-29	51.377 mi
Registration #19	2018-05-29	51.377 mi
Registration #20	2018-05-29	51.377 mi
Registration #21	2018-05-29	51.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1636 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1445 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D039079