



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Silver
Year of manufacture	2007
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	B







## Internet history

### Entry 5

Date 2021-07-26

Pictures 20

Listing price [View report](#)





source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 4

Date 2021-07-09

Pictures 20

Listing price [View report](#)





source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date 2021-06-25

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2



Date 2021-06-08

Pictures

20

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date



2021-05-24

Pictures

20

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-06
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	50
Total items failed	21

MOT #26	2024-03-07 08:31
MOT test number	653123778794
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Suspension component corroded but not seriously weakened rear axle (5.3.3 (b) (i))
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**MOT #25**

2024-03-06 11:17

**MOT test number**

985023171761

**Result****✗ Failed****Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))**Advice** Suspension component corroded but not seriously weakened rear axle (5.3.3 (b) (i))**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))**MOT #24**

2023-02-22 08:31

**MOT test number**

160173029225

**Result****✓ Passed****Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

**MOT #23**

2023-02-21 12:28

**MOT test number**

674166604370

**Result****✗ Failed****Fail** Rear Exhaust has a major leak of exhaust gases exhaust broken (6.1.2 (a))**Fail** Emissions unable to be completed (8.2.1.2 (d))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))**Fail** Central Rear Service brake excessively binding (1.2.1 (f))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))**MOT #22**

2022-03-03 13:06

**MOT test number**

360015921247

**Result****✓ Passed****Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #21**

2022-03-01 12:25

**MOT test number**

126314257120

**Result****✗ Failed**

- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**MOT #20**

2021-02-23 11:07

**MOT test number**

609544392750

**Result****✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19** 2021-02-19 11:47**MOT test number** 106877570625**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))**MOT #18** 2020-03-04 12:27**MOT test number** 749316821298**Result** ✓ Passed**MOT #17** 2020-03-04 12:27**MOT test number** 901845559233**Result** ✗ Failed**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #16** 2019-03-07 13:36**MOT test number** 954822929901**Result** ✓ Passed**Advice** Nearside outer sill slightly corroded**Advice** Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2018-03-05 15:52**MOT test number** 402332899008**Result** ✓ Passed

- Advice** O/s/f brake binding slightly
- Advice** Rear Brake pipe slightly corroded n/s and o/s (3.6.B.2c)
- Advice** Offside Front tyre worn on inner edge

**MOT #14** 2018-03-05 12:52**MOT test number** 667782562221**Result** ✗ Failed

- Fail** Offside Headlamp aim too low adjuster faulty (1.8)
- Advice** O/s/f brake binding slightly
- Advice** Offside Front tyre worn on inner edge
- Advice** Rear Brake pipe slightly corroded n/s and o/s (3.6.B.2c)

**MOT #13** 2017-03-06 10:29**MOT test number** 533914486698**Result** ✓ Passed**MOT #12** 2017-03-03 16:34**MOT test number** 457376648499**Result** ✗ Failed

- Fail** Nearside Indicator switch faulty (1.4.A.1)

**MOT #11** 2016-10-17 14:34**MOT test number** 466272679115**Result** ✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #10** 2016-10-17 14:34**MOT test number** 749358725668**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2015-10-26 14:07**MOT test number** 695388079140**Result** ✓ Passed**Advice** Both rear tyres perished**MOT #8** 2015-10-26 10:07**MOT test number** 350227112504**Result** ✗ Failed**Advice** Both rear tyres perished**Advice** Nearside Front Tyre worn close to the legal limit 155/65/14 (4.1.E.1)**Fail** Nearside Outer Seat belt anchorage prescribed area is excessively corroded sill (5.2.6)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-10-21 09:48**MOT test number** 946924694227**Result** ✓ Passed**MOT #6** 2014-10-21 09:48**MOT test number** 296954994223**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)

**MOT #5** 2013-10-24 11:00**MOT test number** 439217193298**Result** ✓ Passed**MOT #4** 2012-09-28 09:22**MOT test number** 889312272251**Result** ✓ Passed**MOT #3** 2011-11-15 13:33**MOT test number** 828999511383**Result** ✓ Passed**MOT #2** 2011-11-15 09:51**MOT test number** 809379811378**Result** ✗ Failed**Fail** Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #1** 2010-11-16 12:13**MOT test number** 634350020324**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
6 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	6 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	31
First mileage registration	2007-11-23
Last registration	2024-03-07
Complete history	<a href="#">See info</a>



Registration #1	2007-11-23	21 mi
Registration #2	2010-11-16	17.585 mi
Registration #3	2011-11-15	22.536 mi
Registration #4	2011-11-15	22.536 mi
Registration #5	2012-09-28	25.421 mi
Registration #6	2013-10-24	28.753 mi
Registration #7	2014-10-21	33.559 mi
Registration #8	2015-10-26	38.166 mi
Registration #9	2015-10-26	38.166 mi
Registration #10	2016-10-17	41.094 mi
Registration #11	2016-10-17	41.094 mi
Registration #12	2017-03-03	41.804 mi
Registration #13	2017-03-06	41.804 mi
Registration #14	2018-03-05	50.824 mi
Registration #15	2018-03-05	50.830 mi
Registration #16	2019-03-07	55.150 mi
Registration #17	2019-03-07	55.150 mi
Registration #18	2019-03-07	55.150 mi
Registration #19	2019-03-07	55.150 mi
Registration #20	2019-03-07	55.150 mi
Registration #21	2019-03-07	55.150 mi
Registration #22	2019-03-07	55.150 mi
Registration #23	2019-03-07	55.150 mi
Registration #24	2019-03-07	55.150 mi
Registration #25	2019-03-07	55.150 mi
Registration #26	2019-03-07	55.150 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Engine number

5379325