





report date: 2024-03-29

General information

Make	MINI
Model	CLUBMAN COOPER
Colour	Grey
Year of manufacture	2017
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 4.200 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	2.8 mpg
CO2 emission	121 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-09-10

Pictures 5

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date	2021-09-09
Pictures	5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-09-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	0

MOT #7	2023-09-22 15:27
MOT test number	794932829821
Result	✓ Passed
Next expiry date	2024-09-21

MOT #6		2023-09-22 09:59
MOT test	number	536525555830
Result		X Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2254517 (5.2.3 (e))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2	.3 (d) (i))
Advice	Offside Rear Nail in tyre	
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #5	2022-09-08 09:52
MOT test number	555793274599
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4

Result

PF17WHH

report date: 2024-03-29

2021-09-08 15:31

✓ Passed

MOT test number 254154247488

Result ✓ Passed

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #3 2020-11-06 13:45

MOT test number 111536018514

MOT #2 2020-11-05 14:23

MOT test number 148454347668

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1 2020-06-21 05:19

MOT test number 954709897127

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 21 September 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\sim	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-06-29
Last registration	2023-09-22
Complete history	See info



Registration #1	2017-06-29	24 mi
Registration #2	2020-11-05	39.204 mi
Registration #3	2020-11-06	39.204 mi
Registration #4	2021-09-08	43.792 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	68%
Pedestrian	68%
Safety systems	67%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1441 mm
Length	4253 mm
Wheel base	2670 mm
Kerb weight	1395 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles 2

Engine number F683H501