



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Red
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-24
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #11</b>	2022-02-24 09:58
<b>MOT test number</b>	261625799814
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-02-23

<b>MOT #10</b>	2021-02-22 12:31
<b>MOT test number</b>	655958796062
<b>Result</b>	✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #9</b>	2020-02-14 16:05
<b>MOT test number</b>	912281769230
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2020-02-14 12:54
<b>MOT test number</b>	420992707527
<b>Result</b>	✗ Failed

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

<b>MOT #7</b>	2019-02-12 10:50
<b>MOT test number</b>	341995157581
<b>Result</b>	✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bald inner edge of tyre (5.2.3 (e))

**Advice** Nearside Front Road wheel slightly distorted inner wheel rim slight damage (5.2.2 (c) (i))

**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Rear number plate starting to deteriorate

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush starting to deteriorate (5.3.4 (a) (i))

**MOT #6** 2018-02-23 17:25**MOT test number** 423971826088**Result** ✓ Passed**MOT #5** 2018-02-21 11:36**MOT test number** 202698944828**Result** ✗ Failed**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #4** 2017-02-17 12:00**MOT test number** 732531733343**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #3** 2016-02-22 09:58**MOT test number** 575026083965**Result** ✓ Passed**MOT #2** 2016-02-19 13:02**MOT test number** 927593843802**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-04-10 16:45
MOT test number	467980105167
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YF12OCC
Plate since	2019-03-29
Current registration	YF12OCC
Plate since	2019-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-18
Last registration	2022-02-24
Complete history	<a href="#">See info</a>



Registration #1	2012-06-18	13 mi
Registration #2	2015-04-10	82.258 mi
Registration #3	2016-02-19	108.551 mi
Registration #4	2016-02-22	108.559 mi
Registration #5	2017-02-17	124.536 mi
Registration #6	2018-02-21	134.945 mi
Registration #7	2018-02-23	134.945 mi
Registration #8	2019-02-17	155.555 mi
Registration #9	2019-02-20	155.559 mi
Registration #10	2020-02-15	176.166 mi
Registration #11	2020-02-18	176.170 mi
Registration #12	2021-02-12	196.771 mi
Registration #13	2022-02-24	258.608 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867