





report date: 2024-03-29

General information

Make	PEUGEOT
Model	508 HDI SW ACTIVE
Colour	Silver
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-05
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	12
Total items failed	12

MOT #13	2023-07-06 12:35
MOT test number	609343523021
Result	✓ Passed
Next expiry date	2024-07-05

12	2023-06-15 09:22
est number	516165019013
	X Failed
Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Offside Front Tyre tread pattern not visible over the whole tread area when minim (5.2.3 (e))	mum depth required
Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Offside Front Tyre tread pattern not visible over the whole tread area when mini m (5.2.3 (e)) Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #11	2021-12-10 15:12
MOT test number	172870437762
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10 2021-12-08 10:12

MOT test number 688357291809

Result X Failed

Fail Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Fail Offside Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #9 2020-12-29 10:28

MOT test number 260791344097

Result
✓ Passed

MOT #8 2019-12-20 11:40

MOT test number 802934282008

Result ✓ Passed

MOT #7 2019-11-15 16:27

MOT test number 584265105297

Result X Failed

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #6 2018-10-02 15:20

MOT test number 691118011077

Result ✓ Passed

Advice Fluid leak, but not excessive (8.4.1 (a) (i))

Advice Exhaust has a minor leak of exhaust gases Turbo (6.1.2 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Exhaust has a minor leak of exhaust gases Turbo (6.1.2 (a))

Fail Central Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps all (4.7.1 (b) (ii))

Advice Fluid leak, but not excessive (8.4.1 (a) (i))

MOT test number

602911220348

Result

Advice Front Brake hose slightly deteriorated metal end pipes corroding (3.6.B.4d)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Exhaust has a minor leak of exhaust gases turbo (7.1.2)

Advice Oil leak/s

MOT #3

MOT test number

Result

Advice Exhaust has a minor leak of exhaust gases slight seepage at turbo area (7.1.2)

MOT #2

MOT test number

Passed

Advice Under trays fitted covering some components

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2014-08-30 14:08

MOT test number 838242544293

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NIN.
Plate since	100.00
Current registration	SIZ ZIX
Plate since	
	More info

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-29
Last registration	2023-07-06
Complete history	See info



Registration #1	2011-09-29	6 mi
Registration #2	2014-08-30	46.418 mi
Registration #3	2015-09-28	60.302 mi
Registration #4	2016-09-21	67.618 mi
Registration #5	2017-09-22	76.237 mi
Registration #6	2018-09-26	83.978 mi
Registration #7	2018-10-02	83.978 mi
Registration #8	2019-11-15	94.399 mi
Registration #9		11.777 es
Registration #10		77.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1853 mm
Height	1476 mm
Length	4813 mm
Wheel base	2817 mm
Kerb weight	1578 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	72 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number JBEU3004739