



report date: 2024-03-29

General information

|                     |                        |
|---------------------|------------------------|
| Make                | FORD                   |
| Model               | MONDEO ZETEC 136PS     |
| Colour              | Grey                   |
| Year of manufacture | 2010                   |
| Top speed           | 124 mph                |
| 0 - 60 mph          | 9.6 seconds            |
| Gearbox             | 6 speed Semi-Automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 136 BHP             |
| Max. torque             | 319 Nm at 2.000 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 36.2 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 48.7 mpg            |
| CO2 emission            | 154 g/km            |
| CO2 label               | G                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-08                  |
| Pictures      | 24                          |
| Listing price | <a href="#">View report</a> |



source: yesauto.com



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-02-27 |
| MOT pass rate      | 68 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 6          |
| Total advice items | 52         |
| Total items failed | 12         |

|         |                  |
|---------|------------------|
| MOT #19 | 2024-02-28 16:18 |
|---------|------------------|

|                 |              |
|-----------------|--------------|
| MOT test number | 869002935336 |
|-----------------|--------------|

|        |          |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

|                  |            |
|------------------|------------|
| Next expiry date | 2025-02-27 |
|------------------|------------|

- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge badly worn (5.2.3 (e))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Suspension arm corroded but not seriously weakened all suspension arms (5.3.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #18**

2024-02-22 14:28

**MOT test number**

512724274691

**Result****✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Brake cable damaged (1.1.15 (a))
- Fail** Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge badly worn (5.2.3 (e))
- Advice** Rear Suspension arm corroded but not seriously weakened all suspension arms (5.3.3 (b) (i))
- Advice** Central exhaust heat shield insecure
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #17**

2023-02-20 13:02

**MOT test number**

738103606299

**Result**

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16**

2022-02-07 17:00

**MOT test number**

581565248297

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn close to cords exposed (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn bald (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn close to cords exposed (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn bald (5.2.3 (e))

**MOT #15**

2022-02-02 11:02

**MOT test number**

348874623191

**Result****✗ Failed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn bald (5.2.3 (e))

**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Offside Front Shock absorbers has negligible damping effect (5.3.2 (d))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn close to cords exposed (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn bald (5.2.3 (e))

**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge + cracked/perished and inner edge worn close to cords exposed (5.2.3 (e))

**MOT #14**

2021-02-23 12:21

**MOT test number**

880329340634

**Result****✓ Passed****MOT #13**

2021-02-23 12:21

**MOT test number**

128235589140

**Result****✗ Failed**

**Pass with rectification** Rear Exhaust system insecure (6.1.2 (a))

**MOT #12**

2020-10-26 16:48

**MOT test number**

165426610274

**Result****✓ Passed**

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2019-11-20 10:05**MOT test number** 446826473521**Result** ✓ Passed

- Advice** Rear heat shield loose
- Advice** Steering system slightly rough (upper bearings worn) (2.1.1 (a))
- Advice** Front wipers deteriorated
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10** 2019-11-20 10:05**MOT test number** 983733634204**Result** ✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Front wipers deteriorated
- Advice** Rear heat shield loose
- Advice** Steering system slightly rough (upper bearings worn) (2.1.1 (a))

**MOT #9** 2018-11-12 14:09**MOT test number** 890053610783**Result** ✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #8** 2017-11-20 10:53**MOT test number** 943594048095**Result** ✓ Passed

**MOT #7** 2016-11-15 15:00**MOT test number** 946195703420**Result** ✓ Passed**Advice** Covers fitted**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-11-20 15:28**MOT test number** 877797721120**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2015-11-19 13:37**MOT test number** 446170379371**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Fail** Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2014-11-03 14:49**MOT test number** 225537004372**Result** ✓ Passed**Notice** N/s/r trailing arm bush debonding





|                 |   |
|-----------------|---|
| MOT #3          | 2014-11-03 12:28  |
| MOT test number | 385317304307  |
| Result          | ✗ Failed  |
| Fail            | Nearside Rear Direction indicator incorrect colour (1.4.A.2f) |
| Notice          | N/s/r trailing arm bush debonding                             |
| Fail            | Offside Rear Direction indicator incorrect colour (1.4.A.2f)  |

|                 |                  |
|-----------------|------------------|
| MOT #2          | 2013-11-26 08:45 |
| MOT test number | 719960333380     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2013-10-08 16:50 |
| MOT test number | 715211383223     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
27 February 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 February          |
| <b>Days left</b>        | 277                             |
| <b>MOT expiry date</b>  | 27 February 2025                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|              |        |
|--------------|--------|
| XXXXXX       | XXXXXX |
| XXXXXXXXXXXX | XXXXXX |
| XXXXXXXXXX   | XXXXXX |
| XXXXXX       | XXXXXX |
| XXXXXXXXXXXX | XXXXXX |
| XXXXXXXXXX   | XXXXXX |

More info >

Plate changes

See in this check if this FORD had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  XXXXX |
| Plate since          | 2019-06-29  |
| Current registration |  XXXXX |
| Plate since          | 2019-06-29  |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 21                       |
| First mileage registration | 2010-08-10               |
| Last registration          | 2024-02-28               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2010-08-10 | 24 mi      |
| Registration #2  | 2013-10-08 | 50.794 mi  |
| Registration #3  | 2013-11-26 | 50.798 mi  |
| Registration #4  | 2014-11-03 | 59.996 mi  |
| Registration #5  | 2014-11-03 | 59.996 mi  |
| Registration #6  | 2015-11-19 | 70.220 mi  |
| Registration #7  | 2015-11-20 | 70.222 mi  |
| Registration #8  | 2016-11-15 | 79.498 mi  |
| Registration #9  | 2017-11-20 | 87.728 mi  |
| Registration #10 | 2018-11-12 | 97.249 mi  |
| Registration #11 | 2019-11-20 | 111.405 mi |
| Registration #12 | 2020-05-20 | 125.557 mi |
| Registration #13 | 2020-05-20 | 125.557 mi |
| Registration #14 | 2020-05-20 | 125.557 mi |
| Registration #15 | 2020-05-20 | 125.557 mi |
| Registration #16 | 2020-05-20 | 125.557 mi |
| Registration #17 | 2020-05-20 | 125.557 mi |
| Registration #18 | 2020-05-20 | 125.557 mi |
| Registration #19 | 2020-05-20 | 125.557 mi |
| Registration #20 | 2020-05-20 | 125.557 mi |
| Registration #21 | 2020-05-20 | 125.557 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2019 mm |
| Height              | 1500 mm |
| Length              | 4337 mm |
| Wheel base          | 2640 mm |
| Max. allowed weight | 1950 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 53 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |



**Engine number**

AB89987